



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 4211 MLK Jr Way
Date: 08-12-2026

Site ID : OAKF001

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Dan Traffic System	1.0.7.705.02	e0e183ee557189cd059c0ff96f718b8878f36f068fca08f6e59b51de5c3427	
Client Code	1.0.7.705.02	CAQAK	
Location	1.0.7.705.02	NB 4211 MLK JR WAY	
Site Id	1.0.7.705.02	DAKF001	
Container Code	1.0.7.705.02	DAKF001	
Product Serial Number	1.0.7.705.02	B8250603532	
Product Code	1.0.7.705.02	E.02.3.0001 - A42	
EPU XB-CB	XB_1.5.3	S. No: 1423724201218	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2c422b8e77ddac72a6686c74992fe3f263dd6e027e9916d5efea6812b4	http://127.0.0.1:3540
EO-1678-S.NO:576V0	1.0	http://127.0.0.1:5590/skinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-344	S. No: Dn00461A6	http://127.0.0.1:3540
Speed Sensor	FSS-344	FW: 4.93.08.0 - [8]	http://127.0.0.1:3540
Speed Sensor	FSS-344	Checksum: 0X000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6f9-custom	B910e1b0c0dd86bcbf9757c4d5d6da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.064V	OK	http://127.0.0.1:3540
Input Current	1.328A	OK	http://127.0.0.1:3540
External Storage Usage	1,8T 1,4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	400 240 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.162.127	Netmask: 255.255.255.224, Broadcast: 10.244.162.159	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	26 °C	852dcff2c422b8e77ddac72a6686c74992fe3f263dd6e027e9916d5efea6812b4	http://127.0.0.1:3540
GPU Temperature	25.5 °C	852dcff2c422b8e77ddac72a6686c74992fe3f263dd6e027e9916d5efea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 4211 MLK Jr Way
Date: 08-12-2026

Site ID : OAKF002

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Elkin Traffic System	1.0.7.705.02	9d84b922b0d287cd014f94c9ec2f1865e580a673432298b6b87ca701cd220a0b	
Client Code	1.0.7.705.02	CADAK	
Location	1.0.7.705.02	SR 4211 MLK JR WAY	
Site Id	1.0.7.705.02	OAKF002	
Container Code	1.0.7.705.02	OAKF002	
Product Serial Number	1.0.7.705.02	BS250602531	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU X8-CB	X8_1.5.3	S. No: 1421725051662	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8e27ddac72a6686c749929e3f263d8e027e3916d5efce812b4	http://127.0.0.1:3540
EO-1676-S.No:067PZ	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0a000461A8	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [v]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481456	http://127.0.0.1:3540
Epson	2.1.176.1dffe6f8-custom	8910e1b0c0d886bcb9757c8dd06de12	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.066V	OK	http://127.0.0.1:3540
Input Current	1.408A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.162.169	Netmask: 255.255.255.224, Broadcast: 10.244.162.191	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	25 °C	852dcff2d22b8e27ddac72a6686c749929e3f263d8e027e3916d5efce812b4	http://127.0.0.1:3540
GPU Temperature	24.5 °C	852dcff2d22b8e27ddac72a6686c749929e3f263d8e027e3916d5efce812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 5995 Claremont Ave
Date: 08-12-2026

Site ID : OAKF003

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Ekin Traffic System	1.0.7.705.02	9ec1470041792a7ab24f688553909f-659711044526c-d6f40e40M5E7989G002	
Client Code	1.0.7.705.02	CADAK	
Location	1.0.7.705.02	NB 5995 CLAREMONT AVE	
Site Id	1.0.7.705.02	OAKF002	
Container Code	1.0.7.705.02	OAKF003	
Product Serial Number	1.0.7.705.02	BS250603536	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU X9-08	X9_1.5.3	S. No: 1421725051095	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf72d22b8a27dda72a6f88c74992b3f263dd6a027c3916d5e5ea6812b4	http://127.0.0.1:3540
EC-1676-S.No:067PZ	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0a50046320	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.02.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X000000010481A56	http://127.0.0.1:3540
Epon	2.1.176.1df4ef6f8custom	8910e1b0c0d856bdc9757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.048V	OK	http://127.0.0.1:3540
Input Current	1.688A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.243.73	Netmask: 255.255.255.224, Broadcast: 10.244.243.95	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	26.5 °C	852dcf72d22b8a27dda72a6f88c74992b3f263dd6a027c3916d5e5ea6812b4	http://127.0.0.1:3540
GPU Temperature	26 °C	852dcf72d22b8a27dda72a6f88c74992b3f263dd6a027c3916d5e5ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: SB 5995 Claremont Ave
Date: 08-12-2026

Site ID : OAKF004

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info



Edin Traffic System	1.0.7.705.02	554e92a3e6c65d632506c78647bf7988451c23be077c6d161822546cc875434	
Client Code	1.0.7.705.02	CAQAK	
Location	1.0.7.705.02	SB 5995 CLAREMONT AVE	
Site Id	1.0.7.705.02	OAKF004	
Container Code	1.0.7.705.02	OAKF004	
Product Serial Number	1.0.7.705.02	B52596a3530	
Product Code	1.0.7.705.02	E.02.3.3001 - A45	
CPU XB-CB	XB_1.5.3	S. No: 1421725951681	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27dda72e6686c749929e3f262d8a027e3916d5efce6812b4	http://127.0.0.1:3540
ED-1676-S.NO-076TF	1.0	http://127.0.0.1:9595/edinCamera	http://127.0.0.1:3540
Speed Sensor	F89-244	S. No: 0u00848945	http://127.0.0.1:3540
Speed Sensor	F89-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	F89-244	Checksum: 0X000000010481A56	http://127.0.0.1:3540
Epson	2.1.176.1df4e6f8-custom	8910e1b0c0d4868bcf8757c4dd36da12	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.056V	OK	http://127.0.0.1:3540
Input Current	1.4A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	400 240 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.244.73	Netmask: 255.255.255.224, Broadcast: 10.244.244.95	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	25.5 °C	852dcff2d22b8a27dda72e6686c749929e3f262d8a027e3916d5efce6812b4	http://127.0.0.1:3540
GPU Temperature	25.5 °C	852dcff2d22b8a27dda72e6686c749929e3f262d8a027e3916d5efce6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 2424 Foothill Blvd
Date: 08-13-2026

Site ID : OAKF005

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES _____

Housing, poles Locked & secured upon arrival: Clean camera

YES _____


Enforcement signs Present

YES _____

System functionality Verified

YES _____

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info



Skin Traffic System	1.0.7.705.02	8705007e95cae57a2e07de344e328e05be50b1a72a5fcc901f249be10dad721	
Client Code	1.0.7.705.02	CADAK	
Location	1.0.7.705.02	EB 3424 FOOTHILL BLVD	
Site Id	1.0.7.705.02	QAKF005	
Container Code	1.0.7.705.02	QAKF005	
Product Serial Number	1.0.7.705.02	80250603529	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
GPU X9-C8	X9_1.5.3	S. No: 1423724321482	http://127.0.0.1:3540
Radio Server	1.0.7.705.02	852dcf2c22b8a27ddac72a688c74992fc3f63dd6a027e9916d5efea6812b4	http://127.0.0.1:3540
ED-1676-SMO-076V0	1.0	http://127.0.0.1:9590/skinCamera	http://127.0.0.1:3540
Speed Sensor	F89-244	S. No: 0x000461AC	http://127.0.0.1:3540
Speed Sensor	F89-244	FW: 4.83.08.0 - [0]	http://127.0.0.1:3540
Speed Sensor	F89-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Egon	2.1.176.1d84e6f9-custom	8919e1b0c0d4865b0c8757c4d836da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.048V	OK	http://127.0.0.1:3540
Input Current	1.512A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.245.73	Netmask: 255.255.255.224, Broadcast: 10.244.245.95	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Http Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	25.5 °C	852dcf2c22b8a27ddac72a688c74992fc3f63dd6a027e9916d5efea6812b4	http://127.0.0.1:3540
GPU Temperature	25.5 °C	852dcf2c22b8a27ddac72a688c74992fc3f63dd6a027e9916d5efea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 2424 Foothill Blvd

Site ID : OAKF006

Date: 08-13-2026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES

Housing, poles Locked & secured upon arrival: Clean camera

YES

Enforcement signs Present

YES

System functionality Verified

YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				×
Ekin Traffic System	1.0.7.705.02	b7fb287d7fc5beff49469547d4d2518250a58c6b8c32cabcf9b381bf5d334b7		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	WB 2424 FOOTBALL BLVD		
Site Id	1.0.7.705.02	DAKF006		
Container Code	1.0.7.705.02	DAKF006		
Product Serial Number	1.0.7.705.02	B8250602616		
Product Code	1.0.7.705.02	E.02.3.0001 - A48		
EPU X8-C8	X8_1.5.3	S. No: 1421725051493	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c749929c3f262d66ac27c3916d5e6ea6212b4	http://127.0.0.1:3540	
EO-1676-S.NO:076V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0x009488A2	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.53.08.0 - [8]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0d68b6bc8f5757c4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.04V	OK	http://127.0.0.1:3540	
Input Current	1.344A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.47 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 26G 69%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.51.41	Netmask: 255.255.255.224, Broadcast: 10.244.51.63	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	24.5 °C	852dcff2d22b8a27ddac72a6686c749929c3f262d66ac27c3916d5e6ea6212b4	http://127.0.0.1:3540	
GPU Temperature	25.5 °C	852dcff2d22b8a27ddac72a6686c749929c3f262d66ac27c3916d5e6ea6212b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 2005 Foothill Blvd

Site ID : OAKF007

Date: 08-13-2026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES

Housing, poles Locked & secured upon arrival: Clean camera

YES

Enforcement signs Present

YES

System functionality Verified

YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Skin Traffic System	1.0.7.705.02	7d9b5ek294c0bbe66acc0622534132c0c0e187f2c05b942225b9f9b69692		
Client Code	1.0.7.705.02	CA04K		
Location	1.0.7.705.02	EB 2005 FOOTBALL BLVD		
Site Id	1.0.7.705.02	0AKF007		
Container Code	1.0.7.705.02	0AKF007		
Product Serial Number	1.0.7.705.02	86250653513		
Product Code	1.0.7.705.02	E.02.3.0001 - A49		
CPU X8-CB	X8_1.5.3	S. No: 1421725051476		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dc9f2c22b9a27d6ac72a6686c749929c3f263d46a027c2916d5efca812b4		http://127.0.0.1:3540
EO-1676-S.HO-076RC	1.0	http://127.0.0.1:3590/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 3a0064889C		http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.02.08.0 - [9]		http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X000000010481A56		http://127.0.0.1:3540
Epson	2.1.176.1d94e69b-custom	8910e1b0c0dd8b6bdc9757cdd436da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.002V	OK		http://127.0.0.1:3540
Input Current	1.752A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.2T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.44.137	Netmask: 255.255.255.224, Broadcast: 10.244.44.159		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	25 °C	852dc9f2c22b9a27d6ac72a6686c749929c3f263d46a027c2916d5efca812b4		http://127.0.0.1:3540
GPU Temperature	25 °C	852dc9f2c22b9a27d6ac72a6686c749929c3f263d46a027c2916d5efca812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

le

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 2005 Foothill Blvd

Site ID : OAKF008

Date: 08-13-2026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES _____

Housing, poles Locked & secured upon arrival: Clean camera

YES _____

Enforcement signs Present

YES _____

System functionality Verified

YES _____

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	291a1c1dfeb83677529d9eb3288186e96fc0a784d5116ea1cd25d2b04658e475		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	WB 2805 FOOTHILL BLVD		
Site Id	1.0.7.705.02	OAKF008		
Container Code	1.0.7.705.02	OAKF008		
Product Serial Number	1.0.7.705.02	R6250602512		
Product Code	1.0.7.705.02	E.02.3.0001 - A42		
EPU XB-C8	XB_1.5.3	S. No: 1421725051528	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27dda72a6686c749929e2f262dd6a027e3916d5efce6812b4	http://127.0.0.1:3540	
EO-1676-S-NG-076RD	1.0	http://127.0.0.1:9890/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 8a0004C146	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [6]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epson	2.1.176.1df4edf9-custom	8910e1b0c0dd96bdcf8757c4dd35da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.048V	OK		http://127.0.0.1:3540
Input Current	1.252A	OK		http://127.0.0.1:3540
External Storage Usage	1.5T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.48.41	Netmask: 255.255.255.224, Broadcast: 10.244.48.63		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	26.5 °C	852dcff2d22b8a27dda72a6686c749929e2f262dd6a027e3916d5efce6812b4	http://127.0.0.1:3540	
GPU Temperature	26.5 °C	852dcff2d22b8a27dda72a6686c749929e2f262dd6a027e3916d5efce6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 1035 7th St
Date: 08-12-2026

Site ID : OAKF009

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Skid Traffic System	1.0.7.705.02	2838181182e4f85e35609f82495d45c23f28458e7defa5ef8e7495a894c72		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	EB 1035 7TH ST		
Site Id	1.0.7.705.02	OAKF009		
Container Code	1.0.7.705.02	OAKF009		
Product Serial Number	1.0.7.705.02	85250602515		
Product Code	1.0.7.705.02	E.02.2.0001 - A43		
EFU XS-08	X8_1.5.3	S. No: 1423734321419		http://127.0.0.1:2540
Radar Server	1.0.7.705.02	852dcff2d22b8a2788ac72a6686c749929c3f62d68a027c3916d5efad812b4		http://127.0.0.1:2540
EC-1676-S.NO-076V1	1.0	http://127.0.0.1:9590/velin/Camera		http://127.0.0.1:2540
Speed Sensor	FSS-244	S. No: 5e6004EC2A		http://127.0.0.1:2540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [B]		http://127.0.0.1:2540
Speed Sensor	FSS-244	Checksum: 0X000000010481A56		http://127.0.0.1:2540
Ejner	2.1.176.1d46d8f9-custom	991De1b6c0dd86b6c9f737c46d36da13		http://127.0.0.1:2540
Camera Manager	1.1.17	OK		http://127.0.0.1:2540
Input Voltage	5.064V	OK		http://127.0.0.1:2540
Input Current	1.408A	OK		http://127.0.0.1:2540
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:2540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:2540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:2540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:2540
Network Configuration	10.244.52.41	Netmask: 255.255.255.224, Broadcast: 10.244.52.63		http://127.0.0.1:2540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:2540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:2540
Overview	192.168.12.16	Accessible		http://127.0.0.1:2540
Ntp Service	1.0	OK		http://127.0.0.1:2540
CPU Temperature	26 °C	852dcff2d22b8a2788ac72a6686c749929c3f62d68a027c3916d5efad812b4		http://127.0.0.1:2540
GPU Temperature	25.5 °C	852dcff2d22b8a2788ac72a6686c749929c3f62d68a027c3916d5efad812b4		http://127.0.0.1:2540
Database Storage Usage	357M	OK(Folder Size)		http://127.0.0.1:2540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: WB 1014 7th St
Date: 08-12-2026

Site ID : OAKF010

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Elkin Traffic System	1.0.7.705.02	d278f56b9a099c8ebf5e20e94b067322e1ea3c3fed7056eaa7c6f9a52c84f48	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	WB 1014 7TH ST	
Site Id	1.0.7.705.02	QAAKF010	
Container Code	1.0.7.705.02	QAAKF010	
Product Serial Number	1.0.7.705.02	98250683512	
Product Code	1.0.7.705.02	E.02.3.0001 - A49	
EPU X9-C9	X9_1.5.3	S. No: 1423724221479	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf7d22b9a27d6ac72a6686c749929c3f263dd6a027c916d5fede6812b4	http://127.0.0.1:3540
EO-1676-S.NO-076RM	1.0	http://127.0.0.1:9896/ElkinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 2a00046C26	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epson	2.1.176.1d4e6f8b-custom	8910e150c0d4d863dc69757c4d63f6de12	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.096V	OK	http://127.0.0.1:3540
Input Current	1.252A	OK	http://127.0.0.1:3540
External Storage Usage	1.6T 1.21 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	400 240 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.53.201	Netmask: 255.255.255.224, Broadcast: 10.244.53.223	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Http Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	25.5 °C	852dcf7d22b9a27d6ac72a6686c749929c3f263dd6a027c916d5fede6812b4	http://127.0.0.1:3540
GPU Temperature	25.5 °C	852dcf7d22b9a27d6ac72a6686c749929c3f263dd6a027c916d5fede6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 1055 W Grand Ave

Site ID : OAKF011

Date: 08-12-2026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES

YES

Housing, poles Locked & secured upon arrival: Clean camera

Enforcement signs Present

YES

System functionality Verified

YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Edin Traffic System	1.0.7.705.02	d9271c19f8a528b79ccz2f48b98a1d1ed29f058197f9d1cbb1c58279a410e58		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	EB 1055 W GRAND AVE		
Site Id	1.0.7.705.02	OAKF011		
Container Code	1.0.7.705.02	OAKF011		
Product Serial Number	1.0.7.705.02	98250603513		
Product Code	1.0.7.705.02	E.02.2.0001 - A43		
EPU X9-C8	X9_1.5.3	S. No: 1421725051614	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcf2d22b8a27ddac72a6686c749929c3f262dd6a027e3916d5feda6812b4	http://127.0.0.1:3540	
ED-1676-S.NO-076RC	1.0	http://127.0.0.1:3590/edinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-344	S. No: 0a00049025	http://127.0.0.1:3540	
Speed Sensor	FSS-344	FW: 4.03.08.0 - [B]	http://127.0.0.1:3540	
Speed Sensor	FSS-344	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1d4e6f9-custom	8910e1b0c0d686bbcf9757c4dd3d6da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.022V	OK	http://127.0.0.1:3540	
Input Current	1.266A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.54.201	Netmask: 255.255.255.224, Broadcast: 10.244.54.223	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	21 °C	852dcf2d22b8a27ddac72a6686c749929c3f262dd6a027e3916d5feda6812b4	http://127.0.0.1:3540	
GPU Temperature	31.5 °C	852dcf2d22b8a27ddac72a6686c749929c3f262dd6a027e3916d5feda6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: WB 1050 W Grand Ave
Date: 08-12-2026

Site ID : OAKF012

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	dc9c26813d851f225bde4ed2c56a49747b650ed82a2a6c19177e5f5164dc796		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	WB 1050 W GRAND AVE		
Site Id	1.0.7.705.02	OAKF012		
Container Code	1.0.7.705.02	OAKF012		
Product Serial Number	1.0.7.705.02	85250602510		
Product Code	1.0.7.705.02	E.02.2.0001 - A45		
EPU X8-C8	X8_1.5.1	S. No: 1423724221420	http://127.0.0.1:3540	
Radler Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916dd6fca6812b4	http://127.0.0.1:3540	
EO-1676-6-NO-07X45	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-344	S. No: 0a0004892E	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [6]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: DX0000000010481A56	http://127.0.0.1:3540	
Epon	2.1.176.1d4e6f8-custom	8910e1b0c0dd868bcbf957c4dd36da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.064V	OK	http://127.0.0.1:3540	
Input Current	1.405A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.2T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.58.169	Netmask: 255.255.255.224, Broadcast: 10.244.58.191	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Http Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	29.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916dd6fca6812b4	http://127.0.0.1:3540	
GPU Temperature	31 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916dd6fca6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: NB 2710 Broadway
Date: 08-13-2026

Site ID : OAKF013

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
	YES
Housing, poles Locked & secured upon arrival: Clean camera	
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Elkin Traffic Systems	1.0.7.705.02	788a05ec40b43019548f262c1e00945cc2e1b5a714490b7f29ca7edc771779		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	MG 2710 BROADWAY		
Site Id	1.0.7.705.02	QAKF013		
Container Code	1.0.7.705.02	QAKF013		
Product Serial Number	1.0.7.705.02	B0250603511		
Product Code	1.0.7.705.02	E.02.2.0001 - A4G		
EPU X9-GB	X8_1.5.3	S. No: 1421725051671	http://127.0.0.1:9540	
Radar Server	1.0.7.705.02	852acff2d22b8a27ddac72a6686c74992fe3f263dd6a027e3916d5feca6812b4	http://127.0.0.1:9540	
EO-1678-G.N0:57X4P	1.0	http://127.0.0.1:9580/elkinCamera	http://127.0.0.1:9540	
Speed Sensor	FSS-244	S. No: 0a000485CE	http://127.0.0.1:9540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [8]	http://127.0.0.1:9540	
Speed Sensor	FSS-244	Checksum: 0X000000010481A56	http://127.0.0.1:9540	
Epson	2.1.176.1df4ed69-custom	8910e1b0c0d486bbcf8757c4dd36da13	http://127.0.0.1:9540	
Camera Manager	1.1.17	OK	http://127.0.0.1:9540	
Input Voltage	5.048V	OK	http://127.0.0.1:9540	
Input Current	1.32A	OK	http://127.0.0.1:9540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:9540	
Internal Storage Usage	400 240 64%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:9540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:9540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:9540	
Network Configuration	10.244.59.169	Netmask: 255.255.255.224, Broadcast: 10.244.59.191	http://127.0.0.1:9540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:9540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:9540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:9540	
Ntp Service	1.0	OK	http://127.0.0.1:9540	
CPU Temperature	26.5 °C	852acff2d22b8a27ddac72a6686c74992fe3f263dd6a027e3916d5feca6812b4	http://127.0.0.1:9540	
GPU Temperature	26 °C	852acff2d22b8a27ddac72a6686c74992fe3f263dd6a027e3916d5feca6812b4	http://127.0.0.1:9540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 2735 Broadway
Date: 08-13-2026

Site ID : OAKF014

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
Housing, poles Locked & secured upon arrival: Clean camera	YES
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Skia Traffic System	1.8.7.705.02	ea7a43fe3da706dc7da724b57428627fa72526d5a0328ba7875a8c204b4d123		
Client Code	1.8.7.705.02	CADAK		
Location	1.8.7.705.02	GB 3735 BROADWAY		
Site Id	1.8.7.705.02	OAKF014		
Container Code	1.8.7.705.02	OAKF014		
Product Serial Number	1.8.7.705.02	BS250603508		
Product Code	1.8.7.705.02	E.02.3.9001 - A43		
EPU X8-C8	X8_1.5.2	S. No: 1421725051443		http://127.0.0.1:3540
Radar Server	1.8.7.705.02	852dcff2d22bba27ddac72a6686c74992fe3f262dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
EO-1676-S.HO-075KV	1.0	http://127.0.0.1:9590/skinCamera		http://127.0.0.1:3540
Speed Sensor	F88-244	S. No: 9a000488051		http://127.0.0.1:3540
Speed Sensor	F88-244	FW: 4.03.08.0 - [6]		http://127.0.0.1:3540
Speed Sensor	F88-244	Checksum: 6X000000010481A56		http://127.0.0.1:3540
Egms	2.1.176.1d84d6B-custom	8910e1b0c3dd886c87873c8dd68da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.049V	OK		http://127.0.0.1:3540
Input Current	1.416A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.8T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 28G 70%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.200.73	Netmask: 255.255.255.224, Broadcast: 10.244.200.95		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Map Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	26 °C	852dcff2d22bba27ddac72a6686c74992fe3f262dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
GPU Temperature	25.5 °C	852dcff2d22bba27ddac72a6686c74992fe3f262dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
Vibration Enabled	1.8.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2564 San Pablo Ave
Date: 08-12-2026

Site ID : OAKF015

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Elkin Traffic System	1.0.7.705.02	0a744418db76749503280d7b0bde909e02c21d7ac21ff2161faaccdd366e803		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	NB 2564 SAN PABLO AVE		
Site Id	1.0.7.705.02	OAKF015		
Container Code	1.0.7.705.02	OAKF015		
Product Serial Number	1.0.7.705.02	BS2S06032509		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-CB	X8_1.5.3	S. No: 1421723051674		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
EO-1676-S.NO.076V0	1.0	http://127.0.0.1:9990/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0a00649010		http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]		http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A5A		http://127.0.0.1:3540
Epron	2.1.176.1d4ef8b-custom	8910e1b0c0dd86bdcf8757c4dd36da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.088V	OK		http://127.0.0.1:3540
Input Current	1.536A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.204.41	Netmask: 255.255.255.224, Broadcast: 10.244.204.63		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	27.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
GPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

ke

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 2551 San Pablo Ave
Date: 08-12-2026

Site ID : OAKF016

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Skin Traffic System	1.0.7.705.02	ff9ff9d3ceea69d51985052a0e9d56222c3c41b730c7883d2a41875a3b8055a9		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	SB 2551 SAN PABLO AVE		
Site Id	1.0.7.705.02	OAKF016		
Container Code	1.0.7.705.02	OAKF016		
Product Serial Number	1.0.7.705.02	03230603546		
Product Code	1.0.7.705.02	E.02.3.0001 - A42		
CPU X8-08	X8_1.5.3	S. No: 1423724321341	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22bfa27ddac72a6686c749929e3f263dd6a027e3916d5efea812b4	http://127.0.0.1:3540	
EC-1676-S.NO-07N8G	1.0	http://127.0.0.1:3590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0e0054ED38	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.02.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epmr	2.1.176.1d94e649-custom	8910e1b0c0dd96b8c9b757c4d436da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.09V	OK	http://127.0.0.1:3540	
Input Current	1.352A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.344.205.41	Netmask: 255.255.255.224, Broadcast: 10.344.205.43	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Htp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	30 °C	852dcff2d22bfa27ddac72a6686c749929e3f263dd6a027e3916d5efea812b4	http://127.0.0.1:3540	
GPU Temperature	30 °C	852dcff2d22bfa27ddac72a6686c749929e3f263dd6a027e3916d5efea812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 452 7th St
08-12-2026
Date: _____

Site ID : OAKF017

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES _____
	YES _____
Housing, poles Locked & secured upon arrival: Clean camera	_____
Enforcement signs Present	YES _____
System functionality Verified	YES _____

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	5d876672b5e59ed2468dc7f2c4c6ebd15e93b7472644d4d90d49cc96546e191		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	EB 452 7TH ST		
Site Id	1.0.7.705.02	DAKF017		
Container Code	1.0.7.705.02	DAKF017		
Product Serial Number	1.0.7.705.02	98258K02547		
Product Code	1.0.7.705.02	E.02.2.8001 - A48		
CPU X8-CB	X8_1.5.3	S. No: 1421725051486		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852d4ff2d22b4c27dbac72e6686c748928c3f243d46e027e2916d5edeb812b4		http://127.0.0.1:3540
ED-1676-9-NO-07N6W	1.0	http://127.0.0.1:3590/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x00040298		http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]		http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Epron	2.1.176.1d4ef8-custom	8910e1b0c0db85b0c9737c4d4d5de12		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.054V	OK		http://127.0.0.1:3540
Input Current	1.276A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	400 25G 65%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.206.201	Netmask: 255.255.255.224, Broadcast: 10.244.206.223		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	28 °C	852d4ff2d22b4c27dbac72e6686c748928c3f243d46e027e2916d5edeb812b4		http://127.0.0.1:3540
GPU Temperature	27 °C	852d4ff2d22b4c27dbac72e6686c748928c3f243d46e027e2916d5edeb812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 4635 Macarthur Blvd
08-11-2026
Date: _____

Site ID : OAKF018

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES

YES

Housing, poles Locked & secured upon arrival: Clean camera


Enforcement signs Present

YES

System functionality Verified

YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Elon Traffic System	1.0.7.705.02	5a149ddc0b44623884511e81e1ec7712a960e7777416f916eb743e466af448af		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	EB 4635 MACARTHUR BLVD		
Site Id	1.0.7.705.02	OAKF018		
Container Code	1.0.7.705.02	OAKF018		
Product Serial Number	1.0.7.705.02	B0250603545		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X9-CB	X9_1.5.3	S. No: 1421725051434		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27d8ac72a6d86c74992fc3f262dd6e027e2916d5efea6812b4		http://127.0.0.1:3540
EO-1676-SNO-076V0	1.0	http://127.0.0.1:9590/elonCamera		http://127.0.0.1:3540
Speed Sensor	F59-244	S. No: 0x0004ED30		http://127.0.0.1:3540
Speed Sensor	F59-244	FW: 4.03.08.0 - [N]		http://127.0.0.1:3540
Speed Sensor	F59-244	Checksum: 0X000000010481A56		http://127.0.0.1:3540
Epon	2.1.176.1d46d69-custom	9910e1b0c0dd866bc9757c4d036da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.056V	OK		http://127.0.0.1:3540
Input Current	1.808A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	400 22G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.164.105	Netmask: 255.255.255.224, Broadcast: 10.244.164.127		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	20.5 °C	852dcff2d22b8a27d8ac72a6d86c74992fc3f262dd6e027e2916d5efea6812b4		http://127.0.0.1:3540
GPU Temperature	29.5 °C	852dcff2d22b8a27d8ac72a6d86c74992fc3f262dd6e027e2916d5efea6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		http://127.0.0.1:3540

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: WB 4635 Macarthur Blvd
Date: 08-11-2026

Site ID : OAKF019

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	e91b995488895872c2e3bcf0e537582ac7bbfb36a9511b92f881f93f0468f9b		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	WB 4635 MACARTHUR BLVD		
Site Id	1.0.7.705.02	DAKF019		
Container Code	1.0.7.705.02	DAKF019		
Product Serial Number	1.0.7.705.02	BB250603544		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
CPU X8-CB	X8_1.5.3	S. No: 1421725051484	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcf2d22b8a27ddac72a6886c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
EC-1676-S.MO-076V0	1.0	http://127.0.0.1:3590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 6x0004EAC3	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.93.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epan	2.1.176.1df4e6f8-custom	8910e1b0c0d486b8c8f9757c4d436de13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.04V	OK	http://127.0.0.1:3540	
Input Current	1.616A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.2T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.207.201	Netmask: 255.255.255.224, Broadcast: 10.244.207.223	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Http Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	30 °C	852dcf2d22b8a27ddac72a6886c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
GPU Temperature	30.5 °C	852dcf2d22b8a27ddac72a6886c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Le

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2374 Fruitvale Ave
Date: 08-13-2026

Site ID : OAKF020

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
Housing, poles Locked & secured upon arrival: Clean camera	YES
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Elkin Traffic System	1.0.7.705.02	fc97e007184cc0a86fc145258df09e0772d138e21b657de3432eaf7293e1970	
Client Code	1.0.7.705.02	CAQAK	
Location	1.0.7.705.02	NB 2274 FORTVALE AVE	
Site Id	1.0.7.705.02	0A6F020	
Container Code	1.0.7.705.02	0A6F020	
Product Serial Number	1.0.7.705.02	80250602542	
Product Code	1.0.7.705.02	E.02.1.0001 - A42	
EPU X8-08	X8_1.5.3	S. No: 1421725051505	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8e27ddac72a6686c749929c3f263dd6a027e2916cd5ef6a6812b4	http://127.0.0.1:3540
EO-1676-S.NO-076V0	1.0	http://127.0.0.1:3580/ElkinCamera	http://127.0.0.1:3540
Speed Sensor	FS9-244	S. No: 5d0004ED02	http://127.0.0.1:3540
Speed Sensor	FS9-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FS9-244	Checksum: 03D000000010481A58	http://127.0.0.1:3540
Epson	2.1.176.1df4edfb-custom	8910e1b0c0dd86b6cf9757e4dd36de13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.048V	OK	http://127.0.0.1:3540
Input Current	1.416A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.18.10	Netmask: 255.255.255.0, Broadcast: 192.168.18.255	http://127.0.0.1:3540
Network Configuration	10.244.165.105	Netmask: 255.255.255.224, Broadcast: 10.244.165.127	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	26 °C	852dcff2d22b8e27ddac72a6686c749929c3f263dd6a027e2916cd5ef6a6812b4	http://127.0.0.1:3540
GPU Temperature	27 °C	852dcff2d22b8e27ddac72a6686c749929c3f263dd6a027e2916cd5ef6a6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 2500 Fruitvale Ave
Date: 08-13-2026

Site ID : OAKF021

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
Housing, poles Locked & secured upon arrival: Clean camera	YES
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Elkin Traffic System	1.0.7.708.02	bc7a1e9ba227f8605a1ba20827c1d38c209128e9c1722227b251d64728bc63fd		
Client Code	1.0.7.708.02	GADAK		
Location	1.0.7.708.02	SB 2500 FRUITVALE AVE		
Site Id	1.0.7.708.02	OAKF021		
Container Code	1.0.7.708.02	OAKF021		
Product Serial Number	1.0.7.708.02	B0206602541		
Product Code	1.0.7.708.02	E.02.3.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1421725051666	http://127.0.0.1:3540	
Radar Server	1.0.7.708.02	B52dcf92d22bba27ddac72a6686c74992fc3f262bd6a027e3916d5efcead812b4	http://127.0.0.1:3540	
EO-1676-6.NC-078V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0a0004EB26	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epson	2.1.178.1d84edf9-custom	B910e1b0c0d6d6b6bc6f757c4d6d6da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.058V	OK	http://127.0.0.1:3540	
Input Current	1.486A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.27 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 240 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.166.106	Netmask: 255.255.255.224, Broadcast: 10.244.166.127	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Http Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	25 °C	B52dcf92d22bba27ddac72a6686c74992fc3f262bd6a027e3916d5efcead812b4	http://127.0.0.1:3540	
GPU Temperature	24.3 °C	B52dcf92d22bba27ddac72a6686c74992fc3f262bd6a027e3916d5efcead812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.708.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 4001 International Blvd
Date: 08-12-2026

Site ID : OAKF022

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
Housing, poles Locked & secured upon arrival: Clean camera	YES
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	722ba7f6d36cab057c5d893e78bb435a4c290da0ab5b0b9e491427166b06e34		
Client Code	1.0.7.705.02	GADAK		
Location	1.0.7.705.02	EB 4001 INTERNATIONAL BLVD		
Site Id	1.0.7.705.02	OAKF022		
Container Code	1.0.7.705.02	OAKF022		
Product Serial Number	1.0.7.705.02	9S250602540		
Product Code	1.0.7.705.02	E.02.3.0001 - A4Q		
CPU X8-08	X8_1.5.3	S. No: 1422724321373		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8e27d6ac72ae686c749926c3f262dd6a027e3916d5efee6812b4		http://127.0.0.1:3540
EO-1676-9.N0-076T7	1.0	http://127.0.0.1:9890/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0a0004EC42		http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.02.08.0 - [B]		http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Eyon	2.1.176.1d4e6f8-custom	8910e190c0d8d6bbcf9757c8dd36da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.04V	OK		http://127.0.0.1:3540
Input Current	1.4A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.167.105	Netmask: 255.255.255.224, Broadcast: 10.244.167.127		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	32.5 °C	852dcff2d22b8e27d6ac72ae686c749926c3f262dd6a027e3916d5efee6812b4		http://127.0.0.1:3540
GPU Temperature	32.3 °C	852dcff2d22b8e27d6ac72ae686c749926c3f262dd6a027e3916d5efee6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: WB 4000 International Blvd
Date: 08-12-2026

Site ID : OAKF023

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info					✕
Elkin Traffic System	1.0.7.705.02	f19b69375b29a56e2eccc8e66b5b3970c2a2ce640f51d2ad0521464b0582531			
Client Code	1.0.7.705.02	CAOAK			
Location	1.0.7.705.02	WB 4000 INTERNATIONAL BLVD			
Site Id	1.0.7.705.02	DAKF022			
Container Code	1.0.7.705.02	DAKF022			
Product Serial Number	1.0.7.705.02	B825060539			
Product Code	1.0.7.705.02	E.02.3.5001 - A43			
EPU XB-CB	XB_1.5.3	S. No: 1421725051294		http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262d86a027e3916d5efea812b4		http://127.0.0.1:3540	
ED-1676-S.NO.076RJ	1.0	http://127.0.0.1:5990/ElkinCamera		http://127.0.0.1:3540	
Speed Sensor	F89-244	S. No: 0a0004ED39		http://127.0.0.1:3540	
Speed Sensor	F89-244	FW: 4.03.08.0 - [9]		http://127.0.0.1:3540	
Speed Sensor	F89-244	Checksum: 0X000000010481A56		http://127.0.0.1:3540	
Epson	2.1.176.1d4edf8-custom	B910e1b0c0d48664dc9f757c4d456da12		http://127.0.0.1:3540	
Camera Manager	1.1.17	OK		http://127.0.0.1:3540	
Input Voltage	5.032V	OK		http://127.0.0.1:3540	
Input Current	1.488A	OK		http://127.0.0.1:3540	
External Storage Usage	1.8T 1.9T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540	
Internal Storage Usage	40G 23G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540	
Network Configuration	10.244.195.72	Netmask: 255.255.255.224, Broadcast: 10.244.195.95		http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540	
Ntp Service	1.0	OK		http://127.0.0.1:3540	
CPU Temperature	21.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262d86a027e3916d5efea812b4		http://127.0.0.1:3540	
GPU Temperature	21.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262d86a027e3916d5efea812b4		http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes			

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB Hegenberger Rd @ Spencer St
Date: 08-11-2026

Site ID : OAKF024

Physical Inspection Checklist


Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info					X
Ekin Traffic System	1.0.7.705.02	92fec7801526d0a3269d23dbfba058749db5e0937407ea805b76071dd3988ec6			
Client Code	1.0.7.705.02	CAQAK			
Location	1.0.7.705.02	NB HEGENBERGER RD @ SPOENCER ST			
Site Id	1.0.7.705.02	DAKF024			
Container Code	1.0.7.705.02	OAKF024			
Product Serial Number	1.0.7.705.02	B9250603538			
Product Code	1.0.7.705.02	E.02.3.0001 - A43			
EPU X8-C8	X8_1.5.3	S. No: 1421725051444		http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff0d22b8a27ddac72a6686c74992fc3f263dd6a027e3916d5edca812b4		http://127.0.0.1:3540	
EC-1676-S.H0-076R8	1.0	http://127.0.0.1:9990/ekinCamera		http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0a0004E02F		http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.04.08.0 - [H]		http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540	
Epson	2.1.176.1df4e6fb-custom	8910e1b0c0dd8b4bbcf8757c44d36de13		http://127.0.0.1:3540	
Camera Manager	1.1.17	OK		http://127.0.0.1:3540	
Input Voltage	5.064V	OK		http://127.0.0.1:3540	
Input Current	1.488A	OK		http://127.0.0.1:3540	
External Storage Usage	1.8T 1.8T 76%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540	
Network Configuration	10.244.239.9	Netmask: 255.255.255.224, Broadcast: 10.244.239.31		http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540	
Ntp Service	1.0	OK		http://127.0.0.1:3540	
CPU Temperature	31 °C	852dcff0d22b8a27ddac72a6686c74992fc3f263dd6a027e3916d5edca812b4		http://127.0.0.1:3540	
GPU Temperature	31.5 °C	852dcff0d22b8a27ddac72a6686c74992fc3f263dd6a027e3916d5edca812b4		http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes			

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB Hegenberger Rd @ Spencer St
Date: 08-11-2026

Site ID : OAKF025

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Elon Traffic System	1.0.7.705.02	456803809486d350980489572fa61806eb35ac9e7516E79d61fb0e5c70a6008		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	SB HEGENBERGER RD @ SPENCER ST		
Site Id	1.0.7.705.02	OAKF025		
Container Code	1.0.7.705.02	OAKF025		
Product Serial Number	1.0.7.705.02	B92508G3695		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
CPU X8-OS	X8_1.5.3	S. No: 1421425028027	http://127.0.0.1:2540	
Radar Server	1.0.7.705.02	852dcf92422b8a27ddac72a6686c749929c3f652d6fa027e3916d5efca8812b4	http://127.0.0.1:2540	
EO-1676-SNO-G7NG6	1.0	http://127.0.0.1:9890/elonCamera	http://127.0.0.1:2540	
Speed Sensor	FSS-244	S. No: 0x0004E234	http://127.0.0.1:2540	
Speed Sensor	FSS-244	FW: 4.00.08.0 - [6]	http://127.0.0.1:2540	
Speed Sensor	FSS-244	Checksum: 0X000000010481A56	http://127.0.0.1:2540	
Epson	2.1.176.10f4e6f8-cuamr	8910e1b0c0dd8b6bdc95757c8dd436de13	http://127.0.0.1:2540	
Camera Manager	1.1.17	OK	http://127.0.0.1:2540	
Input Voltage	5.02V	OK	http://127.0.0.1:2540	
Input Current	1.616A	OK	http://127.0.0.1:2540	
External Storage Usage	1.8T 899G 54%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:2540	
Internal Storage Usage	49G 25G 65%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:2540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:2540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:2540	
Network Configuration	10.244.17.169	Netmask: 255.255.255.224, Broadcast: 10.244.17.191	http://127.0.0.1:2540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:2540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:2540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:2540	
Ntp Service	1.0	OK	http://127.0.0.1:2540	
CPU Temperature	31.5 °C	852dcf92422b8a27ddac72a6686c749929c3f652d6fa027e3916d5efca8812b4	http://127.0.0.1:2540	
GPU Temperature	22 °C	852dcf92422b8a27ddac72a6686c749929c3f652d6fa027e3916d5efca8812b4	http://127.0.0.1:2540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2206 73rd Ave
Date: 08-11-2026

Site ID : OAKF026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info



Ekin Traffic System	1.0.7.705.02	db9cb33b54bd65176bfdd4828e61b0c2f63d1d08c08a61e12554a788f80164	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	NB 2206 73RD AVE	
Site Id	1.0.7.705.02	QAKF026	
Container Code	1.0.7.705.02	QAKF026	
Product Serial Number	1.0.7.705.02	88250602735	
Product Code	1.0.7.705.02	E.02.3.9001 - A43	
EPU XB-CB	XB_1.5.3	S. No: 1421425027995	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf2d22b8a27ddac72a6686c748929c3f263dd6a027c9916d5efca6812b4	http://127.0.0.1:3540
EO-1676-S.ND:57X19	1.0	http://127.0.0.1:9990/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FS9-244	S. No: 0x0004ED2E	http://127.0.0.1:3540
Speed Sensor	FS9-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FS9-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1d4e68b-custom	8910e1b0c0dd86bcb9757c4d36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.048V	OK	http://127.0.0.1:3540
Input Current	1.472A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 64%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.199.233	Netmask: 255.255.255.234, Broadcast: 10.244.199.255	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	26 °C	852dcf2d22b8a27ddac72a6686c748929c3f263dd6a027c9916d5efca6812b4	http://127.0.0.1:3540
GPU Temperature	26 °C	852dcf2d22b8a27ddac72a6686c748929c3f263dd6a027c9916d5efca6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	



By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: NB 2345 73rd Ave
Date: 08-11-2026

Site ID : OAKF027

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
Housing, poles Locked & secured upon arrival: Clean camera	YES
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Elkin Traffic System	1.0.7.705.02	9573628252e0d7e0e565927e1d4330c0d6e7f20f205e23e4b3e3086813b6e	
Client Code	1.0.7.705.02	OAKAK	
Location	1.0.7.705.02	SB 2345 73RD AVE	
Site Id	1.0.7.705.02	OAKF027	
Container Code	1.0.7.705.02	OAKF027	
Product Serial Number	1.0.7.705.02	95250603722	
Product Code	1.0.7.705.02	E.02.3.0001 - A49	
EPU X8-C8	X8_1.5.3	S. No: 1421425037563	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	8526e9f2d22b8e27dbac72e6686c74992fe3f263dd6a027e0916d5efce6812b4	http://127.0.0.1:3540
ED-1676-S.NQ576V0	1.0	http://127.0.0.1:9090/elkinCamera	http://127.0.0.1:3540
Speed Sensor	F95-244	S. No: 0a0004ED35	http://127.0.0.1:3540
Speed Sensor	F95-244	FW: 4.03.06.0 - [v]	http://127.0.0.1:3540
Speed Sensor	F95-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epson	2.1.176.1df4e5f8-custom	8910e1b0c0dd868bcf8757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.048V	OK	http://127.0.0.1:3540
Input Current	1.552A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	400 240 64%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.200.169	Netmask: 255.255.255.224, Broadcast: 10.244.200.191	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Wip Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	27 °C	8526e9f2d22b8e27dbac72e6686c74992fe3f263dd6a027e0916d5efce6812b4	http://127.0.0.1:3540
GPU Temperature	26.5 °C	8526e9f2d22b8e27dbac72e6686c74992fe3f263dd6a027e0916d5efce6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	http://127.0.0.1:3540

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 8648 Bancroft Ave
Date: 08-11-2026

Site ID : OAKF028

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES

Housing, poles Locked & secured upon arrival: Clean camera	YES

Enforcement signs Present	YES

System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				×
Ekin Traffic System	1.0.7.705.02	52c9c5d712a0f90fb1cd93d6bcadbc04a579ebcd8f15c292401537154cb77a90c		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	MB 8648 BANCROFT AVE		
Site Id	1.0.7.705.02	OAKF028		
Container Code	1.0.7.705.02	OAKF028		
Product Serial Number	1.0.7.705.02	B8250904049		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
CPU X8-C8	X8_1.5.3	S. No: 1421425038129	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2c22b8e27ddac72a6686c749929c3f262d6dc027e3916d5efee812b4	http://127.0.0.1:3540	
EO-1676-S.NO.07NCJ	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 9e004ED45	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.00.00.0 - [N]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Egson	2.1.176.16f4ef9-custom	8910e1b0c0d68f6bcb9757c6Ad936de13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.056V	OK	http://127.0.0.1:3540	
Input Current	1.304A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 22G 57%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.204.127	Netmask: 255.255.255.0, Broadcast: 10.244.204.255	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	25 °C	852dcff2c22b8e27ddac72a6686c749929c3f262d6dc027e3916d5efee812b4	http://127.0.0.1:3540	
GPU Temperature	24.5 °C	852dcff2c22b8e27ddac72a6686c749929c3f262d6dc027e3916d5efee812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 8605 Bancroft Ave
Date: 08-11-2026

Site ID : OAKF029

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Ekin Traffic System	1.0.7.705.02	x72c8995485bffa94f7ab5ccc6d82c9b6685d5507e38b869c4287017ce08e3d58	
Client Code	1.0.7.705.02	CAQAK	
Location	1.0.7.705.02	38 8605 BANCROFT AVE	
Site Id	1.0.7.705.02	OAKF029	
Container Code	1.0.7.705.02	OAKF029	
Product Serial Number	1.0.7.705.02	88250803730	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPJ X8-C8	X8_1.B.3	S. No: 1421425027513	http://127.0.0.1:2540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c749929c3f262d6a027e3916d5efce6812b4	http://127.0.0.1:2540
EC-1676-G.NG-07NH6	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:2540
Speed Sensor	F89-244	S. No: 0a0004EDC7	http://127.0.0.1:2540
Speed Sensor	F89-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:2540
Speed Sensor	F89-244	Checksum: 0X0000000010481A56	http://127.0.0.1:2540
Epron	2.1.176.1df4ef8-custom	891De1b0c0dd86abc95757c4dd36de13	http://127.0.0.1:2540
Camera Manager	1.1.17	OK	http://127.0.0.1:2540
Input Voltage	5.072V	OK	http://127.0.0.1:2540
Input Current	1.456A	OK	http://127.0.0.1:2540
External Storage Usage	1.8T 1.2T 76%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:2540
Internal Storage Usage	40G 23G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:2540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:2540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:2540
Network Configuration	10.244.205.127	Netmask: 255.255.255.224, Broadcast: 10.244.205.159	http://127.0.0.1:2540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:2540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:2540
Overview	192.168.12.16	Accessible	http://127.0.0.1:2540
Ntp Service	1.0	OK	http://127.0.0.1:2540
CPU Temperature	25.5 °C	852dcff2d22b8a27ddac72a6686c749929c3f262d6a027e3916d5efce6812b4	http://127.0.0.1:2540
GPU Temperature	25 °C	852dcff2d22b8a27ddac72a6686c749929c3f262d6a027e3916d5efce6812b4	http://127.0.0.1:2540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 998 98th Ave
Date: 08-11-2026

Site ID : OAKF030

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES

YES

Housing, poles Locked & secured upon arrival: Clean camera

Enforcement signs Present

YES

System functionality Verified

YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	93d51aa3c8193b9872b772965934c298f1abe81d4d7c05e7545c0e930511ae7e		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	MS-998 96TH AVE		
Site Id	1.0.7.705.02	OAKF030		
Container Code	1.0.7.705.02	OAKF030		
Product Serial Number	1.0.7.705.02	89250802721		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X9-G8	X8_1.5.3	S. No: 1421425337960	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dc9f3d22b6a27d4ac72a6686c749929c3f262d46a027e3916d5e0ea6812b4	http://127.0.0.1:3540	
EO-1676-S.HQ.07N0V	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0a00049020	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1d4e6f8-custom	8910e1b0c0b086b0c6757c4dd0bde12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.016V	OK	http://127.0.0.1:3540	
Input Current	1.696A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 25G 66%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.344.206.41	Netmask: 255.255.255.224, Broadcast: 10.344.206.63	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.14	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	34.5 °C	852dc9f3d22b6a27d4ac72a6686c749929c3f262d46a027e3916d5e0ea6812b4	http://127.0.0.1:3540	
GPU Temperature	25 °C	852dc9f3d22b6a27d4ac72a6686c749929c3f262d46a027e3916d5e0ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 998 98th Ave
Date: 08-11-2026

Site ID : OAKF031

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Elon Traffic System	1.0.7.705.02	1a155132b394de38c714fa7267b5d1e99e1e74eac05b2f6d15b5dec2b38e0ea7		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	98 998 98TH AVE		
Site Id	1.0.7.705.02	DAKF021		
Container Code	1.0.7.705.02	DAKF021		
Product Serial Number	1.0.7.705.02	88250603728		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X9-C8	X8_1.5.3	S. No: 1424524914814	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2c22bba27d4ac72a6686c74992fc3f262dd6a027e3916d5e6ea812b4	http://127.0.0.1:3540	
ED-1676-S.NO:07NH7	1.0	http://127.0.0.1:9590/elonCamera	http://127.0.0.1:3540	
Speed Sensor	FSD-244	S. No: 0x000489CA	http://127.0.0.1:3540	
Speed Sensor	FSD-244	FW: 4.02.08.0 - [8]	http://127.0.0.1:3540	
Speed Sensor	FSD-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1d4edf9-custom	8910e1b0c0dd8d6b0cf9757c4d536da1a	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.024V	OK	http://127.0.0.1:3540	
Input Current	1.512A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.47 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	400 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.287.41	Netmask: 255.255.255.224, Broadcast: 10.244.287.63	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Http Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	25 °C	852dcff2c22bba27d4ac72a6686c74992fc3f262dd6a027e3916d5e6ea812b4	http://127.0.0.1:3540	
GPU Temperature	24.5 °C	852dcff2c22bba27d4ac72a6686c74992fc3f262dd6a027e3916d5e6ea812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 1928 98th Ave
Date: 08-11-2026

Site ID : OAKF032

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info



Ekin Traffic System	1.0.7.705.02	1b5565f126503b4e45652165154a26e1520ee87ee7449e1c4b9d9054910f9906	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	NB 1928 98TH AVE	
Site Id	1.0.7.705.02	OAKF022	
Container Code	1.0.7.705.02	OAKF022	
Product Serial Number	1.0.7.705.02	BS250803729	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
CPU X9-08	X9_1.5.3	S. No: 1424524214519	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c749929c3f243d8a027e3916d5e6a6812b4	http://127.0.0.1:3540
EO-1676-S.NO.076V0	1.0	http://127.0.0.1:5590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	F80-244	S. No: 0a00049023	http://127.0.0.1:3540
Speed Sensor	F80-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	F80-244	Checksum: 0X000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1d84e6f8-custom	8910e1b0c0dd86b8c9757c4dd0da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.032V	OK	http://127.0.0.1:3540
Input Current	1.488A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.8T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.208.41	Netmask: 255.255.255.224, Broadcast: 10.244.208.63	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	25 °C	852dcff2d22b8a27ddac72a6686c749929c3f243d8a027e3916d5e6a6812b4	http://127.0.0.1:3540
GPU Temperature	24 °C	852dcff2d22b8a27ddac72a6686c749929c3f243d8a027e3916d5e6a6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	



By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 1928 98th Ave
Date: 08-11-2026

Site ID : OAKF033

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
Housing, poles Locked & secured upon arrival: Clean camera	YES
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	94e288a24c224ce8a190223366ec9a564234f72a8abb5db2d9719e6770f0d4b		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	SB 1R28 96TH AVE		
Site Id	1.0.7.705.02	OAKF023		
Container Code	1.0.7.705.02	OAKF032		
Product Serial Number	1.0.7.705.02	B6250803727		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
GPU X9-GB	X9_1.5.3	S. No: 1421425037602		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c749925e3f263dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
EO-1676-S.NO:0854R	1.0	http://127.0.0.1:3590/EkinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-344	S. No: B600548BC5		http://127.0.0.1:3540
Speed Sensor	FSS-344	FW: 4.03.08.0 - [8]		http://127.0.0.1:3540
Speed Sensor	FSS-344	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd65b6cf9757c4a63d4e12		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.04V	OK		http://127.0.0.1:3540
Input Current	1.4A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 22G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.240.201	Netmask: 255.255.255.224, Broadcast: 10.244.240.223		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	25.5 °C	852dcff2d22b8a27ddac72a6686c749925e3f263dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
GPU Temperature	25 °C	852dcff2d22b8a27ddac72a6686c749925e3f263dd6a027e3916d5efea6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 6161 Bancroft Ave
Date: 08-11-2026

Site ID : OAKF034

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	edc024d7208d89f36504914f9b89e7dbcbef529eade532d2288c3d4dce737a		
Client Code	1.0.7.705.02	QADAK		
Location	1.0.7.705.02	EB 6161 BANCROFT AVE		
Site Id	1.0.7.705.02	QAKF034		
Container Code	1.0.7.705.02	QAKF034		
Product Serial Number	1.0.7.705.02	B9250802726		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1421429037719	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c749929c3f262ddca027e3916d5efca6812b4	http://127.0.0.1:3540	
EO-1676-SINO-07NCT	1.0	http://127.0.0.1:9890/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 8a00049054	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [a]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.175.1d4e6f9-custom	8910e1b0c0dd86bbc9f757c4dd36de13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.002V	OK	http://127.0.0.1:3540	
Input Current	1.632A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.8T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 246 82%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.241.201	Netmask: 255.255.255.0, Broadcast: 10.244.241.224	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	24.5 °C	852dcff2d22b8a27ddac72a6686c749929c3f262ddca027e3916d5efca6812b4	http://127.0.0.1:3540	
GPU Temperature	25.5 °C	852dcff2d22b8a27ddac72a6686c749929c3f262ddca027e3916d5efca6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victory



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 6130 Bancroft Ave
08-11-2026
Date: _____

Site ID : OAKF035

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES _____
Housing, poles Locked & secured upon arrival: Clean camera	YES _____
Enforcement signs Present	YES _____
System functionality Verified	YES _____

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	efdc222f186ea4b7638ef8bba70ca1fc9f1a679092216941e265c8c5d79a03e		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	WR 6130 SANCROFT AVE		
Site Id	1.0.7.705.02	DAKF025		
Container Code	1.0.7.705.02	DAKF025		
Product Serial Number	1.0.7.705.02	83250602543		
Product Code	1.0.7.705.02	E.02.3.9001 - A43		
EPU X9-CB	X8_1.5.3	S. No: 1422724221422		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf7d422b8a27d8ac72a6688c749929c3f262dd8a027e2916d5efca6812b4		http://127.0.0.1:3540
EO-1676-SINO-S76WM	1.0	http://127.0.0.1:3595/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-344	S. No: 5a00048E3C		http://127.0.0.1:3540
Speed Sensor	FSS-344	FW: 4.03.08.0 - [9]		http://127.0.0.1:3540
Speed Sensor	FSS-344	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Egon	2.1.176.1d4e6f8-custom	8910e1b0c0d48f83bc8f57c4dd26da12		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.04V	OK		http://127.0.0.1:3540
Input Current	1.472A	OK		http://127.0.0.1:3540
External Storage Usage	1.6T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.242.201	Netmask: 255.255.255.234, Broadcast: 10.244.242.223		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	25 °C	852dcf7d422b8a27d8ac72a6688c749929c3f262dd8a027e2916d5efca6812b4		http://127.0.0.1:3540
GPU Temperature	25.5 °C	852dcf7d422b8a27d8ac72a6688c749929c3f262dd8a027e2916d5efca6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo