

VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: NB 4211 MLK Jr Way
Date: 07-19-2026
Site ID : OAKF001

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	e0e180ee537189cb059c0ff06f71868878f06f063facab86e93b51de5c53427		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	NB 4211 MLK JR WAY		
Site Id	1.0.7.705.02	OAKF001		
Container Code	1.0.7.705.02	OAKF001		
Product Serial Number	1.0.7.705.02	B8250603532		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1423724321218		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8e27ddac72a6686c749925e3f263d86e027e3916d5e5e6812b4		http://127.0.0.1:3540
ED-1676-S.NO.076V0	1.0	http://127.0.0.1:9990/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0e000461A6		http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]		http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Epron	2.1.176.1d4e6f9-custom	8910e1b0c0d48648c8f8757c44d36da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.048V	OK		http://127.0.0.1:3540
Input Current	1.576A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 23G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.163.127	Netmask: 255.255.255.224, Broadcast: 10.244.163.159		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessbile		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	36.5 °C	852dcff2d22b8e27ddac72a6686c749925e3f263d86e027e3916d5e5e6812b4		http://127.0.0.1:3540
GPU Temperature	36.5 °C	852dcff2d22b8e27ddac72a6686c749925e3f263d86e027e3916d5e5e6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 4211 MLK Jr Way
Date: 07-16-2026


Site ID : OAKF002

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	0cb95886b7218fcca4d371ce05fc31b1a33229e0e4c2e9d1e2f8189d529e8e8		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	SB 4211 MLK JR WAY		
Site Id	1.0.7.705.02	QAKF002		
Container Code	1.0.7.705.02	QAKF002		
Product Serial Number	1.0.7.705.02	98250602531		
Product Code	1.0.7.705.02	E.02.3.0001 - A42		
EPU X8-C8	X8_1.5.3	S. No: 1421725051662	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8e27ddbc72a6686c749929c3f263d86e027c0916d5efcead812b4	http://127.0.0.1:3540	
EO-1676-S.No:067PZ	1.0	http://127.0.0.1:9090/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	F89-244	S. No: 0x000461A8	http://127.0.0.1:3540	
Speed Sensor	F89-244	FW: 4.03.08.0 - [0]	http://127.0.0.1:3540	
Speed Sensor	F89-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4edf6-custom	8910e1b0c0d486b6c8757c4a63564e13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.048V	OK	http://127.0.0.1:3540	
Input Current	1.824A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 65%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.163.169	Netmask: 255.255.255.224, Broadcast: 10.244.163.191	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Http Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	35 °C	852dcff2d22b8e27ddbc72a6686c749929c3f263d86e027c0916d5efcead812b4	http://127.0.0.1:3540	
GPU Temperature	35 °C	852dcff2d22b8e27ddbc72a6686c749929c3f263d86e027c0916d5efcead812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 5995 Claremont Ave
Date: 07-19-2026


Site ID : OAKF003

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	9ee1470041793a7ab24f686b5390fc659711094526c6a840e49f5079f8902		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	NB 8995 CLAREMONT AVE		
Site Id	1.0.7.705.02	OAKF003		
Container Code	1.0.7.705.02	OAKF003		
Product Serial Number	1.0.7.705.02	B6250603536		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-CB	X8_1.5.3	S. No: 1421725051295		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf02d22b8a27ddac72a6686c74992fc3f263dd5a027e3916d5e6ea6812b4		http://127.0.0.1:3540
EO-1676-S.No:067PZ	1.0	http://127.0.0.1:9590/ekinCamera		http://127.0.0.1:3540
Speed Sensor	F89-244	S. No: 0a00046320		http://127.0.0.1:3540
Speed Sensor	F89-244	FW: 4.03.08.0 - [x]		http://127.0.0.1:3540
Speed Sensor	F89-244	Checksum: 0X0000000015481A56		http://127.0.0.1:3540
Epron	2.1.176.1d46f69-custom	8910e1b0c0d486bdcf9757c4dd36da12		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.056V	OK		http://127.0.0.1:3540
Input Current	1.284A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.2T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.243.79	Netmask: 255.255.255.224, Broadcast: 10.244.243.95		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	30 °C	852dcf02d22b8a27ddac72a6686c74992fc3f263dd5a027e3916d5e6ea6812b4		http://127.0.0.1:3540
GPU Temperature	29.5 °C	852dcf02d22b8a27ddac72a6686c74992fc3f263dd5a027e3916d5e6ea6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 5995 Claremont Ave
Date: 07-16-2026


Site ID : OAKF004

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Elan Traffic System	1.0.7.705.02	554e92a2edc654622506c78847b7990451c22ba07c6d161822546cc875434		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	SB 5995 CLAREMONT AVE		
Site Id	1.0.7.705.02	OAKF004		
Container Code	1.0.7.705.02	OAKF004		
Product Serial Number	1.0.7.705.02	B5250603530		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-08	X8_1.5.3	S. No: 1421725051681	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c749929c3f262dd6e027e9916d5efea6812b4	http://127.0.0.1:3540	
EO-1676-S.NO-076TF	1.0	http://127.0.0.1:9990/elanCamera	http://127.0.0.1:3540	
Speed Sensor	F59-244	S. No: 0x00048946	http://127.0.0.1:3540	
Speed Sensor	F59-244	FW: 4.03.08.0 - [H]	http://127.0.0.1:3540	
Speed Sensor	F59-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f9-custom	8910e1b0c0dd86bcbf757c4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.064V	OK	http://127.0.0.1:3540	
Input Current	1.304A	OK	http://127.0.0.1:3540	
External Storage Usage	1,6T 1,3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.244.73	Netmask: 255.255.255.224, Broadcast: 10.244.244.95	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c749929c3f262dd6e027e9916d5efea6812b4	http://127.0.0.1:3540	
GPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c749929c3f262dd6e027e9916d5efea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 2424 Foothill Blvd
Date: 07-16-2026

Site ID : OAKF005

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
	YES
Housing, poles Locked & secured upon arrival: Clean camera	
Enforcement signs Present	YES
System functionality Verified	YES


Additional Notes



Jul 16, 2026 at 8:38:45 AM
2445 Foothill Blvd
Oakland CA 94601
United States



Jul 16, 2026 at 8:40:26 AM
2442-2474 Foothill Blvd
Oakland CA 94601
United States



TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				
Elkin Traffic System	1.0.7.705.02	8705007495cae97a2ed7dc24da238c05ba50b1a72a5f0c901f24f8a10b3d9f22		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	EB 2424 FOOTHILL BLVD		
Site Id	1.0.7.705.02	DAKF005		
Container Code	1.0.7.705.02	DAKF005		
Product Serial Number	1.0.7.705.02	88250603528		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU XB-CB	XB_1.5.3	S. No: 1423724321482		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992b2f262d6a027e2916d5fca6812b4		http://127.0.0.1:3540
EO-1676-SNO-076V0	1.0	http://127.0.0.1:9990/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSD-244	S. No: 0a000461AC		http://127.0.0.1:3540
Speed Sensor	FSD-244	FW: 4.03.08.0 - [6]		http://127.0.0.1:3540
Speed Sensor	FSD-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Epron	2.1.176.1df4e68b-custom	8910e1b0c0d4d86bcb8757c4dd36da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.04V	OK		http://127.0.0.1:3540
Input Current	1.608A	OK		http://127.0.0.1:3540
External Storage Usage	1,8T 1,4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	400 240 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.245.73	Netmask: 255.255.255.224, Broadcast: 10.244.245.95		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6686c74992b2f262d6a027e2916d5fca6812b4		http://127.0.0.1:3540
GPU Temperature	29 °C	852dcff2d22b8a27ddac72a6686c74992b2f262d6a027e2916d5fca6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 2424 Foothill Blvd
07-16-2026
Date: _____

Site ID : OAKF006

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES

YES


Housing, poles Locked & secured upon arrival: Clean camera

Enforcement signs Present YES

System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Elkin Traffic System	1.0.7.705.02	b79b2f7d7c5beff49469547d4d2518250a58c6b8c32cab9b381bf5d334b7		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	WB 3424 FOOTHILL BLVD		
Site Id	1.0.7.705.02	OAKF006		
Container Code	1.0.7.705.02	OAKF006		
Product Serial Number	1.0.7.705.02	98250603516		
Product Code	1.0.7.705.02	E.02.3.0001 - A42		
EPU X8-C8	X8_1.5.3	S. No: 1421725051433		http://127.0.0.1:9540
Radar Server	1.0.7.705.02	852dff2d22b8a27d4ac72a6686c74992f63f263dd5a027c916d5efead812b4		http://127.0.0.1:9540
EO-1676-S.NO:076V0	1.0	http://127.0.0.1:9595/ekinCamera		http://127.0.0.1:9540
Speed Sensor	FS0-244	S. No: 0a000488A2		http://127.0.0.1:9540
Speed Sensor	FS0-244	FW: 4.03.08.0 - [8]		http://127.0.0.1:9540
Speed Sensor	FS0-244	Checksum: 0X0000000010481A56		http://127.0.0.1:9540
Epson	2.1.176.1df4e6b9-custom	8910e1b0c0d486bdcf8757c6dd36de13		http://127.0.0.1:9540
Camera Manager	1.1.17	OK		http://127.0.0.1:9540
Input Voltage	5.04V	OK		http://127.0.0.1:9540
Input Current	1.368A	OK		http://127.0.0.1:9540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Internal Storage Usage	40G 24G 69%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:9540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:9540
Network Configuration	10.244.51.41	Netmask: 255.255.255.224, Broadcast: 10.244.51.63		http://127.0.0.1:9540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:9540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:9540
Overview	192.168.12.16	Accessible		http://127.0.0.1:9540
Ntp Service	1.0	OK		http://127.0.0.1:9540
CPU Temperature	27.5 °C	852dff2d22b8a27d4ac72a6686c74992f63f263dd5a027c916d5efead812b4		http://127.0.0.1:9540
GPU Temperature	29 °C	852dff2d22b8a27d4ac72a6686c74992f63f263dd5a027c916d5efead812b4		http://127.0.0.1:9540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: EB 2005 Foothill Blvd
Date: 07-16-2026
Site ID : OAKF007

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				
Ekin Traffic System	1.0.7.705.02	746b5eb294c0b5ea66ccc08225554122ccdc187f2cd5b99462225b8f90b9692		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	EB 2005 FOOTHILL BLVD		
Site Id	1.0.7.705.02	OAKF007		
Container Code	1.0.7.705.02	OAKF007		
Product Serial Number	1.0.7.705.02	B5250603512		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1421725051676	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27d4ac72a6686c749929c3f262dd6a027e3916d5efea6812b4	http://127.0.0.1:3540	
EO-1676-S.NO:576RC	1.0	http://127.0.0.1:9590/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0a004889C	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1d84e6f8-custom	8910e1b0c0dd86bbcf6757c4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.04V	OK		http://127.0.0.1:3540
Input Current	1.376A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 29G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.44.137	Netmask: 255.255.255.224, Broadcast: 10.244.44.159		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	28 °C	852dcff2d22b8a27d4ac72a6686c749929c3f262dd6a027e3916d5efea6812b4	http://127.0.0.1:3540	
GPU Temperature	28 °C	852dcff2d22b8a27d4ac72a6686c749929c3f262dd6a027e3916d5efea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 2005 Foothill Blvd
Date: 07-16-2026


Site ID : OAKF008

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES
	YES
Housing, poles Locked & secured upon arrival: Clean camera	
Enforcement signs Present	YES
System functionality Verified	YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				
Ekin Traffic System	1.0.7.705.02	291a1cdfab83677529d9ab3288186e96fc0a784d5116aa1cd25d2b04658e475		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	WB 2005 FOOTHILL BLVD		
Site Id	1.0.7.705.02	OAKF008		
Container Code	1.0.7.705.02	OAKF008		
Product Serial Number	1.0.7.705.02	B8250602513		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1421725051538	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcf2cd22b8a27ddac72a6686c74992fc3f263d86ac027e3916d5efea812b4	http://127.0.0.1:3540	
EO-1676-S.NO.576RC	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	F80-244	S. No: 8a0094C146	http://127.0.0.1:3540	
Speed Sensor	F80-244	FW: 4.03.08.0 - [8]	http://127.0.0.1:3540	
Speed Sensor	F80-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f8-custom	891de1b0c0d8b6bdcf9737c4dd96da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.048V	OK	http://127.0.0.1:3540	
Input Current	1.448A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.48.41	Netmask: 255.255.255.224, Broadcast: 10.244.48.63	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	31 °C	852dcf2cd22b8a27ddac72a6686c74992fc3f263d86ac027e3916d5efea812b4	http://127.0.0.1:3540	
GPU Temperature	31 °C	852dcf2cd22b8a27ddac72a6686c74992fc3f263d86ac027e3916d5efea812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 1035 7th St
07-17-2026
Date: _____


Site ID : OAKF009

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
YES
Housing, poles Locked & secured upon arrival: Clean camera _____
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	bb69c0f55bcb3edafe54be4f43626b72643d5596dad45fcd8547b189ed4ca		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	EB 1035 7TH ST		
Site Id	1.0.7.705.02	OAKF009		
Container Code	1.0.7.705.02	OAKF009		
Product Serial Number	1.0.7.705.02	B025060315		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
CPU X8-C9	X8_1.5.3	S. No: 1423724321419	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6886c74992b3f262dd6a027e3916d5edea6812b4	http://127.0.0.1:3540	
EO-1676-S.NO.076V1	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSD-244	S. No: 0x0004EC2A	http://127.0.0.1:3540	
Speed Sensor	FSD-244	FW: 4.03.08.0 - [H]	http://127.0.0.1:3540	
Speed Sensor	FSD-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1d4edf9-custom	8910e1b0c0dd86bbc8757c0dd36de13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.056V	OK	http://127.0.0.1:3540	
Input Current	1.72A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	400 240 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.52.41	Netmask: 255.255.255.224, Broadcast: 10.244.52.63	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6886c74992b3f262dd6a027e3916d5edea6812b4	http://127.0.0.1:3540	
GPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6886c74992b3f262dd6a027e3916d5edea6812b4	http://127.0.0.1:3540	
Database Storage Usage	324M	OK(Folder Size)	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 1014 7th St
Date: 08-10-2026


Site ID : OAKF010

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	d728f56b9e089c9ebf5e20e94b067522e1ea3c3fed7056aead2e59a62c84f48		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	WB 1014 7TH ST		
Site Id	1.0.7.705.02	OAKF010		
Container Code	1.0.7.705.02	OAKF010		
Product Serial Number	1.0.7.705.02	B8250603512		
Product Code	1.0.7.705.02	E.02.2.0001 - A43		
CPU X8-CB	XR_1.5.3	S. No: 1423724321479	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcf2d22b8a27ddac72a6686c74992fc3f262d6a027c3916d5e5ea6812b4	http://127.0.0.1:3540	
EO-1676-S.NO:076RM	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0a0004EC26	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [x]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1d46ef9-custom	8910e1b0c0d48d5bcbf9757c4dd36da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.088V	OK	http://127.0.0.1:3540	
Input Current	1.536A	OK	http://127.0.0.1:3540	
External Storage Usage	1,8T 1,2T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.53.201	Netmask: 255.255.255.224, Broadcast: 10.244.53.223	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	25 °C	852dcf2d22b8a27ddac72a6686c74992fc3f262d6a027c3916d5e5ea6812b4	http://127.0.0.1:3540	
GPU Temperature	34.5 °C	852dcf2d22b8a27ddac72a6686c74992fc3f262d6a027c3916d5e5ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: EB 1055 W Grand Ave Site ID : OAKF011
 Date: 07-15-2026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
 Housing, poles Locked & secured upon arrival: Clean camera YES
 Enforcement signs Present YES
 System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				
Elan Traffic System	1.0.7.705.02	d9271c198a526b79cc2b48b94e1d1ed29905811979d1c0d61c58379e410e58		
Client Code	1.0.7.705.02	CAOMK		
Location	1.0.7.705.02	EB 1055 W GRAND AVE		
Site Id	1.0.7.705.02	CAKP011		
Container Code	1.0.7.705.02	CAKP011		
Product Serial Number	1.0.7.705.02	86250653013		
Product Code	1.0.7.705.02	E.02.3.0001 - A48		
CPU X8-64	X8_1.5.3	S. No: 1421725051614		http://127.0.0.1:9540
Radex Server	1.0.7.705.02	852a9f0c22b8a276d6c72a6684c749f2b3d53a86a27c9916d5efcead812b4		http://127.0.0.1:9540
SD-1676-6NO-876AC	1.0	http://127.0.0.1:9540 WebCamera		http://127.0.0.1:9540
Speed Sensor	F50-344	S. No: 5e00049025		http://127.0.0.1:9540
Speed Sensor	F50-344	FW: 4.03.08.0 - [E]		http://127.0.0.1:9540
Speed Sensor	F50-344	Checksum: 0X0000000015481A56		http://127.0.0.1:9540
Egmon	2.1.176.1d84e6b8 custom	8910e150c5a893a1e8757c4a55a5d413		http://127.0.0.1:9540
Camera Manager	1.1.17	OK		http://127.0.0.1:9540
Input Voltage	5.032V	OK		http://127.0.0.1:9540
Input Current	1.44A	OK		http://127.0.0.1:9540
External Storage Usage	1.8T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Internal Storage Usage	480 340 69%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Network Configuration	172.17.0.1	Network: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:9540
Network Configuration	192.168.10.10	Network: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:9540
Network Configuration	10.344.54.201	Network: 255.255.255.224, Broadcast: 10.344.54.223		http://127.0.0.1:9540
Network Configuration	192.168.12.10	Network: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:9540
Network Configuration	127.0.0.1	Network: 255.0.0.0		http://127.0.0.1:9540
Overview	192.168.12.14	Accessible		http://127.0.0.1:9540
Rtp Service	1.0	OK		http://127.0.0.1:9540
CPU Temperature	35.5 °C	852a9f0c22b8a276d6c72a6684c749f2b3d53a86a27c9916d5efcead812b4		http://127.0.0.1:9540
GPU Temperature	36 °C	852a9f0c22b8a276d6c72a6684c749f2b3d53a86a27c9916d5efcead812b4		http://127.0.0.1:9540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 1050 W Grand Ave
Date: 07-15-2026


Site ID : OAKF012

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				
Skia Traffic System	1.0.7.705.02	4b9c2d813d81f225b4e4e2c68a8f7479445a822c3a6c19177e95144a4c796		
Client Code	1.0.7.705.02	CADAK		
Location	1.0.7.705.02	WB 1950 W GRAND AVE		
Site Id	1.0.7.705.02	DAK7012		
Container Code	1.0.7.705.02	DAK7012		
Product Serial Number	1.0.7.705.02	B9250603510		
Product Code	1.0.7.705.02	E.02.1.0001 - A48		
EPU X8-GB	X8_1.5.3	S. No: 1422724221420		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	8f24e4f2d22b4e27d6e72e6686c74992e3f53d66e027e2916d5efce6812b4		http://127.0.0.1:3540
EO-1676-S.NO-07X45	1.0	http://127.0.0.1:9990/skinCamera		http://127.0.0.1:3540
Speed Sensor	F50-244	S. No: 0x0004893C		http://127.0.0.1:3540
Speed Sensor	F50-244	FW: 4.03.08.0 - [0]		http://127.0.0.1:3540
Speed Sensor	F50-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Egon	2.1.176.10f4e6f8-custom	8910e190c0d6808bc9f757e44d264e13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.064V	OK		http://127.0.0.1:3540
Input Current	1.44A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1,47 79%	OK[Folder Size/Partition Used/Partition Total Ratio]		http://127.0.0.1:3540
Internal Storage Usage	400 340 53%	OK[Folder Size/Partition Used/Partition Total Ratio]		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.58.169	Netmask: 255.255.255.224, Broadcast: 10.244.58.191		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	33.5 °C	8f24e4f2d22b4e27d6e72e6686c74992e3f53d66e027e2916d5efce6812b4		http://127.0.0.1:3540
GPU Temperature	34.5 °C	8f24e4f2d22b4e27d6e72e6686c74992e3f53d66e027e2916d5efce6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: NB 2710 Broadway
Date: 07-15-2026


Site ID : OAKF013

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				X
Elon Traffic System	1.0.7.705.02	785a05ecf40b430185480243c1e009f45cc3e1b0a79a80b7029ca7ede771779		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	MS 2710 BROADWAY		
Site Id	1.0.7.705.02	QAAQ213		
Container Code	1.0.7.705.02	QAAQ213		
Product Serial Number	1.0.7.705.02	B0250600511		
Product Code	1.0.7.705.02	E.02.3.0001 - A40		
CPU X8-08	X8_1.5.3	S. No: 1421725051471		http://127.0.0.1:9540
Radar Server	1.0.7.705.02	852a0f02d2b0a2788ac72a6686c74992b30263686e027e3916d5efcead812b4		http://127.0.0.1:9540
EO-1676-S-NO-07X4P	1.0	http://127.0.0.1:9580/elonCamera		http://127.0.0.1:9540
Speed Sensor	F80-244	S. No: 5e000485CE		http://127.0.0.1:9540
Speed Sensor	F80-244	FW: 4.03.08.0 - [E]		http://127.0.0.1:9540
Speed Sensor	F80-244	Checksum: 0X000000010481A58		http://127.0.0.1:9540
Egon	2.1.176.1d4d6d9-custom	8910e1b0c0d4d6d9c0f9737c4a0364e13		http://127.0.0.1:9540
Camera Manager	1.1.17	OK		http://127.0.0.1:9540
Input Voltage	5.04V	OK		http://127.0.0.1:9540
Input Current	1.672A	OK		http://127.0.0.1:9540
External Storage Usage	1,81 1,47 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Internal Storage Usage	400 240 60%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:9540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:9540
Network Configuration	10.244.39.169	Netmask: 255.255.255.224, Broadcast: 10.244.39.191		http://127.0.0.1:9540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:9540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:9540
Overview	192.168.12.16	Accessible		http://127.0.0.1:9540
Http Service	1.0	OK		http://127.0.0.1:9540
CPU Temperature	33 °C	852a0f02d2b0a2788ac72a6686c74992b30263686e027e3916d5efcead812b4		http://127.0.0.1:9540
GPU Temperature	32.5 °C	852a0f02d2b0a2788ac72a6686c74992b30263686e027e3916d5efcead812b4		http://127.0.0.1:9540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 2735 Broadway
Date: 07-15-2026


Site ID : OAKF014

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info			
On-Trail System	1.8.7.705.02	es7a43b5b4706b47d4c724b5742b52767262645a3238a7675a4c354b44f123	
Client Code	1.8.7.705.02	CAOMC	
Location	1.8.7.705.02	SB 2725 BROADWAY	
Site ID	1.8.7.705.02	DAK014	
Container Code	1.8.7.705.02	DAK014	
Product Serial Number	1.8.7.705.02	85250633506	
Product Code	1.8.7.705.02	E02.3.0001 - A42	
GPU X8-08	X8_1.5.3	S. No: 1421723551443	http://172.0.0.1:3540
Radar Server	1.8.7.705.02	852a4f0222b8a2746ac72a6686c749f2b3f263a68a027a3916d5edea812b4	http://172.0.0.1:3540
EO-1476-SNO-076XV	1.0	http://172.0.0.1:9590/VideoCamera	http://172.0.0.1:3540
Speed Sensor	F80-244	S. No: 0a0048851	http://172.0.0.1:3540
Speed Sensor	F80-244	FW: 4.03.08.0 - [H]	http://172.0.0.1:3540
Speed Sensor	F80-244	Checksum: 00000000010481A36	http://172.0.0.1:3540
Eggs	2.1.176.1d4ed9-custom	9910e180c0d88b6c46757c4d4064e13	http://172.0.0.1:3540
Camera Manager	1.1.17	OK	http://172.0.0.1:3540
Input Voltage	5.048V	OK	http://172.0.0.1:3540
Input Current	1.384A	OK	http://172.0.0.1:3540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://172.0.0.1:3540
Internal Storage Usage	400 280 70%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://172.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://172.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://172.0.0.1:3540
Network Configuration	10.244.200.73	Netmask: 255.255.255.224, Broadcast: 10.244.200.95	http://172.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://172.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://172.0.0.1:3540
Overview	192.168.12.16	Accessible	http://172.0.0.1:3540
Http Service	1.0	OK	http://172.0.0.1:3540
CPU Temperature	36.5 °C	852a4f0222b8a2746ac72a6686c749f2b3f263a68a027a3916d5edea812b4	http://172.0.0.1:3540
GPU Temperature	36.5 °C	852a4f0222b8a2746ac72a6686c749f2b3f263a68a027a3916d5edea812b4	http://172.0.0.1:3540
Violation Enabled	1.8.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2564 San Pablo Ave
Date: 07-15-2026


Site ID : OAKF015

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Elkin Traffic System	1.0.7.705.02	60c3c46502a69ecdeaf8a906160c7493e9107009a7281e049833aee82148b		
Client Code	1.0.7.705.02	GADAK		
Location	1.0.7.705.02	NB 2564 SAN PABLO AVE		
Site ID	1.0.7.705.02	OAKF015		
Container Code	1.0.7.705.02	OAKF015		
Product Serial Number	1.0.7.705.02	B025060209		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
GPU X8-08	X8_1.5.3	S. No: 1421725051474	http://127.0.0.1:9540	
Radar Server	1.0.7.705.02	853dc4f0d22b8a27ddac72a6686c749926c3f043a68e027e3916d0efcead812b4		http://127.0.0.1:9540
ED-1676-S.NO-076V9	1.0	http://127.0.0.1:9590/vtkinCamera		http://127.0.0.1:9540
Speed Sensor	F9S-244	S. No: 0a00049010	http://127.0.0.1:9540	
Speed Sensor	F9S-244	FW: 4.03.08.0 - [8]	http://127.0.0.1:9540	
Speed Sensor	F9S-244	Checksum: 0X000000010481A56	http://127.0.0.1:9540	
Egion	2.1.176.1684d86-custom	8910e1b0cb08f6b6c8f737c0A036da12		http://127.0.0.1:9540
Camera Manager	1.1.17	OK		http://127.0.0.1:9540
Input Voltage	5.089V	OK		http://127.0.0.1:9540
Input Current	1.464A	OK		http://127.0.0.1:9540
External Storage Usage	1.8T 1.2T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Internal Storage Usage	400 240 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:9540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:9540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:9540
Network Configuration	10.244.204.41	Netmask: 255.255.255.224, Broadcast: 10.244.204.63		http://127.0.0.1:9540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:9540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:9540
Overview	192.168.12.16	Accessible		http://127.0.0.1:9540
Ntp Service	1.0	OK		http://127.0.0.1:9540
CPU Temperature	34.8 °C	853dc4f0d22b8a27ddac72a6686c749926c3f043a68e027e3916d0efcead812b4		http://127.0.0.1:9540
GPU Temperature	35 °C	853dc4f0d22b8a27ddac72a6686c749926c3f043a68e027e3916d0efcead812b4		http://127.0.0.1:9540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 2551 San Pablo Ave
Date: 07-15-2026


Site ID : OAKF016

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	YES _____
	YES _____
Housing, poles Locked & secured upon arrival: Clean camera	_____
Enforcement signs Present	YES _____
System functionality Verified	YES _____

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				✕
Dkin Traffic System	1.0.7.795.02	3b4d6299888b3e5d55c7b699634f2f053e878e959b2108842ebe8044accf869		
Client Code	1.0.7.795.02	CAOAK		
Location	1.0.7.795.02	88 2531 SAN PABLO AVE		
Site Id	1.0.7.795.02	OAK7016		
Container Code	1.0.7.795.02	OAK7016		
Product Serial Number	1.0.7.795.02	80250603546		
Product Code	1.0.7.795.02	E.02.3.0001 - A43		
CPU X8-C8	X8_1.5.3	S. No: 1422734321341		http://127.0.0.1:3540
Radar Server	1.0.7.795.02	853dc4f2d22b8a27ddac72e6686c749926e3f263a89a037e2916d5efeeaf812b4		http://127.0.0.1:3540
EC-1676-SNO-07N80	1.0	http://127.0.0.1:9590/vtkinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-344	S. No: 3a0054E038		http://127.0.0.1:3540
Speed Sensor	FSS-344	FW: 4.03.08.0 - [0]		http://127.0.0.1:3540
Speed Sensor	FSS-344	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Egon	2.1.176.1d4d48-custom	8910e15dc5d4843dc493757c4d436de13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.08V	OK		http://127.0.0.1:3540
Input Current	1.48A	OK		http://127.0.0.1:3540
External Storage Usage	1.8T 1.37 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	400 230 62%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.205.41	Netmask: 255.255.255.224, Broadcast: 10.244.205.63		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	38.5 °C	853dc4f2d22b8a27ddac72e6686c749926e3f263a89a037e2916d5efeeaf812b4		http://127.0.0.1:3540
GPU Temperature	38.5 °C	853dc4f2d22b8a27ddac72e6686c749926e3f263a89a037e2916d5efeeaf812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.795.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 452 7th St
Date: 07-15-2026

Site ID : OAKF017

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES _____

YES _____

Housing, poles Locked & secured upon arrival: Clean camera

Enforcement signs Present


YES _____

System functionality Verified

YES _____

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	6d876673b0e9ded246f6dc7f2c4c6abd15a93b7472644d4d80d4fec6546e191		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	EB 452 7TH ST		
Site Id	1.0.7.705.02	OAKF017		
Container Code	1.0.7.705.02	OAKF017		
Product Serial Number	1.0.7.705.02	BS250603547		
Product Code	1.0.7.705.02	E.02.2.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1421725051486	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c916d5e6ca6812b4	http://127.0.0.1:3540	
ED-1676-S.NO:07N6W	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0x0004ED38	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbcf8757c4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.048V	OK	http://127.0.0.1:3540	
Input Current	1.528A	OK	http://127.0.0.1:3540	
External Storage Usage	1,8T 1,4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.206.201	Netmask: 255.255.255.224, Broadcast: 10.244.206.223	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	23 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c916d5e6ca6812b4	http://127.0.0.1:3540	
GPU Temperature	22 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c916d5e6ca6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 4635 Macarthur Blvd
Date: 07-15-2026

Site ID : OAKF018

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES

Housing, poles Locked & secured upon arrival: Clean camera

YES

Enforcement signs Present

YES

System functionality Verified


YES

Additional Notes

07-15-2026 11:32 AM



07-15-2026 11:34 AM



TECHNICIAN SERVICE AND INSPECTION LOG

System info page


System Info

Ekin Traffic System	1.0.7.705.02	5a149ddc0b4d623884511e81a1ec7712a960a7777416f916eb743e466af448af	
Client Code	1.0.7.705.02	OAKAK	
Location	1.0.7.705.02	EB 4635 MACARTHUR BLVD	
Site Id	1.0.7.705.02	OAKF018	
Container Code	1.0.7.705.02	OAKF018	
Product Serial Number	1.0.7.705.02	BS250603545	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU X8-C8	X8_1.5.3	S. No: 1421725051434	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
EC-1676-S.NO:076V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x0004ED90	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbcf8757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.056V	OK	http://127.0.0.1:3540
Input Current	1.576A	OK	http://127.0.0.1:3540
External Storage Usage	1,8T 1,4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 23G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.164.105	Netmask: 255.255.255.224, Broadcast: 10.244.164.127	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	35.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	34.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 4635 Macarthur Blvd
Date: 07-15-2026


Site ID : OAKF019

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page


System Info

Ekin Traffic System	1.0.7.705.02	e91b99048889f5873c9e3bcf0e637582ac7bbfb36b9511b92f881f93f0468f8b	
Client Code	1.0.7.705.02	CADAK	
Location	1.0.7.705.02	WB 4635 MACARTHUR BLVD	
Site Id	1.0.7.705.02	OAKF019	
Container Code	1.0.7.705.02	OAKF019	
Product Serial Number	1.0.7.705.02	BS250603544	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU XB-CB	XB_1.5.3	S. No: 1421725051484	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916d5e6ea6812b4	http://127.0.0.1:3540
EC-1676-S.NO:076V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0a0004EAC3	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6fb-custom	8910e1b0c0dd86bbcf8757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.04V	OK	http://127.0.0.1:3540
Input Current	1.52A	OK	http://127.0.0.1:3540
External Storage Usage	1,8T 1,3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.207.201	Netmask: 255.255.255.224, Broadcast: 10.244.207.223	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	38.5 °C	852dcf2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	38.5 °C	852dcf2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2374 Fruitvale Ave
Date: 07-15-2026


Site ID : OAKF020

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	045a253b-4d39d161edbf2d90775920946d52d089e6532962d9578b7f72055c7		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	NB 2374 FRUITVALE AVE		
Site Id	1.0.7.705.02	OAKF020		
Container Code	1.0.7.705.02	OAKF020		
Product Serial Number	1.0.7.705.02	BS250603542		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-CB	X8_1.5.3	S. No: 1421725051505		http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4		http://127.0.0.1:3540
EC-1676-S.NO:076V0	1.0	http://127.0.0.1:9590/ekinCamera		http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x0004ED32		http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]		http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56		http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbcf8757c4dd36da13		http://127.0.0.1:3540
Camera Manager	1.1.17	OK		http://127.0.0.1:3540
Input Voltage	5.048V	OK		http://127.0.0.1:3540
Input Current	1.432A	OK		http://127.0.0.1:3540
External Storage Usage	1,8T 1,3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://127.0.0.1:3540
Network Configuration	10.244.165.105	Netmask: 255.255.255.224, Broadcast: 10.244.165.127		http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://127.0.0.1:3540
Ntp Service	1.0	OK		http://127.0.0.1:3540
CPU Temperature	32.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4		http://127.0.0.1:3540
GPU Temperature	33.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4		http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 2500 Fruitvale Ave
Date: 07-15-2026

Site ID : OAKF021

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES


Additional Notes



07-15-2026 10:18 AM



07-15-2026 10:19 AM



TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	bc7a1e8ba227f8605a1ba20837c1d38c209128e9c1732227b251d64728bc63fd		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	SB 2500 FRUITVALE AVE		
Site Id	1.0.7.705.02	OAKF021		
Container Code	1.0.7.705.02	OAKF021		
Product Serial Number	1.0.7.705.02	BS250602541		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-CB	X8_1.5.3	S. No: 1421725051666	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
EC-1676-S.NO-076V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0a0004EB26	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f9-custom	8910e1b0c0dd86bbcf8757c4dd36de13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.056V	OK	http://127.0.0.1:3540	
Input Current	1.352A	OK	http://127.0.0.1:3540	
External Storage Usage	1,8T 1,3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 23G 61%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.166.105	Netmask: 255.255.255.224, Broadcast: 10.244.166.127	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
GPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 4001 International Blvd
Date: 07-15-2026


Site ID : OAKF022

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info




Ekin Traffic System	1.0.7.705.02	6d97b187aee54bc386a228b8c3b95f0c27c55a74fb3ad9cc1871ce66b77bfa43	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	EB 4001 INTERNATIONAL BLVD	
Site Id	1.0.7.705.02	OAKF022	
Container Code	1.0.7.705.02	OAKF022	
Product Serial Number	1.0.7.705.02	BS250603540	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU X8-C8	X8_1.5.3	S. No: 1422724321373	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
EC-1676-S.NO:076T7	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x0004EC42	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd8b6bcbf9757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.032V	OK	http://127.0.0.1:3540
Input Current	1.576A	OK	http://127.0.0.1:3540
External Storage Usage	1,8T 1,2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.167.105	Netmask: 255.255.255.224, Broadcast: 10.244.167.127	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	32.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	32.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 4000 International Blvd
Date: 07-15-2026


Site ID : OAKF023

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page


System Info

Ekin Traffic System	1.0.7.705.02	F19b69375b20a56e2eccc8e66b5b3970c2a2ce640f51d2adc05214d4b0582551	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	WB 4000 INTERNATIONAL BLVD	
Site Id	1.0.7.705.02	OAKF023	
Container Code	1.0.7.705.02	OAKF023	
Product Serial Number	1.0.7.705.02	BS250603539	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU XB-CB	XB_1.5.3	S. No: 1421725051394	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
EO-1676-S.NO.076RJ	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x0004ED39	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbcf8757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.024V	OK	http://127.0.0.1:3540
Input Current	1.768A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.195.73	Netmask: 255.255.255.224, Broadcast: 10.244.195.95	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	29 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB Hegenberger Rd @ Spencer St
Date: 07-16-2026


Site ID : OAKF024

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	3ba76bf2b4ccd66160b39c1c119b21c56a6bb4dcb82aeb091e986d308ffbac2c		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	NB HEGENBERGER RD @ SPENCER ST		
Site Id	1.0.7.705.02	OAKF024		
Container Code	1.0.7.705.02	OAKF024		
Product Serial Number	1.0.7.705.02	BS250603538		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-CB	XB_1.5.3	S. No: 1421725051444	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ca6812b4	http://127.0.0.1:3540	
EC-1676-S.NO:076R8	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0a004ED2F	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbc8b757c4dd36da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.064V	OK	http://127.0.0.1:3540	
Input Current	1.448A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.239.9	Netmask: 255.255.255.224, Broadcast: 10.244.239.31	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ca6812b4	http://127.0.0.1:3540	
GPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ca6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the foregoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB Hegenberger Rd @ Spencer St
Date: 07-16-2026


Site ID : OAKF025

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect	<u>YES</u>
Housing, poles Locked & secured upon arrival: Clean camera	<u>YES</u>
Enforcement signs Present	<u>YES</u>
System functionality Verified	<u>YES</u>

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				×
Ekin Traffic System	1.0.7.705.02	f2dfb998043e35735227c441fe992cfc85ef2d66ddae43a4d201fb4e21fb03f		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	SB HEGENBERGER RD @ SPENCER ST		
Site Id	1.0.7.705.02	OAKF025		
Container Code	1.0.7.705.02	OAKF025		
Product Serial Number	1.0.7.705.02	BS250803695		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU X8-C8	X8_1.5.3	S. No: 1421425038027	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
EO-1676-S.NO-07NG6	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FS9-244	S. No: 0x0004ED34	http://127.0.0.1:3540	
Speed Sensor	FS9-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FS9-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6fb-custom	8910e1b0c0dd86bbcf9757c4dd36da1a	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.032V	OK	http://127.0.0.1:3540	
Input Current	1.48A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 289G 18%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 65%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.17.169	Netmask: 255.255.255.224, Broadcast: 10.244.17.191	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	42.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
GPU Temperature	43 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2206 73rd Ave
Date: 07-14-2026

Site ID : OAKF026

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect

YES _____

Housing, poles Locked & secured upon arrival: Clean camera

YES _____

Enforcement signs Present


YES _____

System functionality Verified

YES _____

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page


System Info

Ekin Traffic System	1.0.7.705.02	9ba1751ba67c7a874f6ef7c0e24065cd65a422cc048a801c8dc6063e53eb2d04	
Client Code	1.0.7.705.02	CAQAK	
Location	1.0.7.705.02	NB 2206 73RD AVE	
Site Id	1.0.7.705.02	OAKF026	
Container Code	1.0.7.705.02	OAKF026	
Product Serial Number	1.0.7.705.02	BS250803735	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU X8-08	X8_1.5.3	S. No: 1421425037895	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcf2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
EC-1676-S.NO:07X19	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FS9-244	S. No: 0a0004ED2E	http://127.0.0.1:3540
Speed Sensor	FS9-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FS9-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6fb-custom	B910e1b0c0dd86bcbf757c4dd36da1a	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.04V	OK	http://127.0.0.1:3540
Input Current	1.864A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 64%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.199.233	Netmask: 255.255.255.224, Broadcast: 10.244.199.255	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	39 °C	852dcf2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	39 °C	852dcf2d22b8a27ddac72a6686c74992fc3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 2345 73rd Ave
Date: 07-14-2026


Site ID : OAKF027

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page


System Info

Ekin Traffic System	1.0.7.705.02	9573628252a03d1e3ee665927e1d4330c0d6e7f20f205c236d0b5a3086815b8d	
Client Code	1.0.7.705.02	CAQAK	
Location	1.0.7.705.02	SB 2245 73RD AVE	
Site Id	1.0.7.705.02	OAKF027	
Container Code	1.0.7.705.02	OAKF027	
Product Serial Number	1.0.7.705.02	BS250603732	
Product Code	1.0.7.705.02	E.02.2.0001 - A43	
EPU X8-C8	X8_1.5.2	S. No: 1421425037563	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
EC-1676-S.NO:076V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x0004ED35	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbcf8757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.04V	OK	http://127.0.0.1:3540
Input Current	1.392A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 64%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.200.169	Netmask: 255.255.255.224, Broadcast: 10.244.200.191	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	43.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	42.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information


Location Address: NB 8648 Bancroft Ave
Date: 07-14-2026
Site ID : OAKF028

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Ekin Traffic System	1.0.7.705.02	52c9c5d712a0890fb1cd93d6bcd8ce4a579ebc6f15c392401537154cb77a90c		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	NB 8648 BANCROFT AVE		
Site Id	1.0.7.705.02	OAKF028		
Container Code	1.0.7.705.02	OAKF028		
Product Serial Number	1.0.7.705.02	BS250904049		
Product Code	1.0.7.705.02	E 02.3.0001 - A43		
EPU X8-CB	X8_1.5.3	S. No: 1421425098129	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027c3916d5e6ca6812b4	http://127.0.0.1:3540	
EC-1676-S.N.O:07NCJ	1.0	http://127.0.0.1:9990/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0x0004EC45	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6fb-custom	8910e1b0c0dd86bcbf8757e4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.048V	OK	http://127.0.0.1:3540	
Input Current	1.432A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 22G 57%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.204.137	Netmask: 255.255.255.0, Broadcast: 10.244.204.255	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	32 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027c3916d5e6ca6812b4	http://127.0.0.1:3540	
GPU Temperature	31.5 °C	852dcff2d22b8a27ddac72a6686c74992fc3f262dd6a027c3916d5e6ca6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 8605 Bancroft Ave
Date: 07-14-2026


Site ID : OAKF029

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				×
Ekin Traffic System	1.0.7.705.02	a72c8995485bfb8a34f7ab5ecb8d82c9b6685d5507e38bd89d287017ce0fe3258		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	SB 9605 BANCROFT AVE		
Site Id	1.0.7.705.02	OAKF029		
Container Code	1.0.7.705.02	OAKF029		
Product Serial Number	1.0.7.705.02	BS250803730		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU XB-CB	XB_1_5.3	S. No: 1421425037513	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
EC-1676-S.N.O:07NH6	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0x0004EDC7	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f9-custom	B910e1b0c0dd86bcbf9757c4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.072V	OK	http://127.0.0.1:3540	
Input Current	1.464A	OK	http://127.0.0.1:3540	
External Storage Usage	1,8T 1,3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.205.137	Netmask: 255.255.255.224, Broadcast: 10.244.205.199	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	41 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
GPU Temperature	40.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 998 98th Ave
Date: 07-14-2026


Site ID : OAKF030

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page


System Info

Ekin Traffic System	1.0.7.705.02	667e1ecc6706aaf2c72267e6b5b1fead4cb1aaf53a6ca192aaf85ea9f1cf49a	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	NB 998 98TH AVE	
Site Id	1.0.7.705.02	OAKF030	
Container Code	1.0.7.705.02	OAKF030	
Product Serial Number	1.0.7.705.02	BS250803731	
Product Code	1.0.7.705.02	E.02.3.0001 - A43	
EPU X8-CB	X8_1.5.3	S. No: 1421425037560	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ca6812b4	http://127.0.0.1:3540
EC-1676-S.NO:07NCV	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x00049020	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6f8-custom	8910e1b0c0dd86bbc9f9757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.024V	OK	http://127.0.0.1:3540
Input Current	1.328A	OK	http://127.0.0.1:3540
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 25G 66%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.206.41	Netmask: 255.255.255.224, Broadcast: 10.244.206.63	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	27.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ca6812b4	http://127.0.0.1:3540
GPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ca6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 998 98th Ave
Date: 07-14-2026


Site ID : OAKF031

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info

Ekin Traffic System	1.0.7.705.02	1a155122b294de38c7f4fa7267b6d1e99e1e74eacd5b2fb615b5dec2b38e0ea7	
Client Code	1.0.7.705.02	CAOAK	
Location	1.0.7.705.02	SB 998 98TH AVE	
Site Id	1.0.7.705.02	OAKF031	
Container Code	1.0.7.705.02	OAKF031	
Product Serial Number	1.0.7.705.02	BS250803728	
Product Code	1.0.7.705.02	E.02.2.0001 - A43	
EPU X8-08	X8_1.5.3	S. No: 1424524314814	http://127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
EO-1676-S.NO:07NH7	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540
Speed Sensor	FSS-244	S. No: 0x000489CA	http://127.0.0.1:3540
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540
Epron	2.1.176.1df4e6fb-custom	8910e1b0c0dd86b6bcfb757c4dd36da13	http://127.0.0.1:3540
Camera Manager	1.1.17	OK	http://127.0.0.1:3540
Input Voltage	5.024V	OK	http://127.0.0.1:3540
Input Current	1.52A	OK	http://127.0.0.1:3540
External Storage Usage	1,8T 1,3T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540
Network Configuration	10.244.207.41	Netmask: 255.255.255.224, Broadcast: 10.244.207.63	http://127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540
Ntp Service	1.0	OK	http://127.0.0.1:3540
CPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
GPU Temperature	27.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e3916d5e6ea6812b4	http://127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes	

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: NB 1928 98th Ave
Date: 07-14-2026

Site ID : OAKF032

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES


Housing, poles Locked & secured upon arrival: Clean camera YES

Enforcement signs Present YES

System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				×
Ekin Traffic System	1.0.7.705.02	1b5565f136503b4e45652165154a26a1520ee87ec7449e1c4b9d054910f2906		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	HB 192B 98TH AVE		
Site Id	1.0.7.705.02	OAKF032		
Container Code	1.0.7.705.02	OAKF032		
Product Serial Number	1.0.7.705.02	BS250802729		
Product Code	1.0.7.705.02	E.02.1.0001 - A43		
EPU X9-C9	X9_1.5.3	S. No: 1424524214519	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e9916d5e6ea6812b4	http://127.0.0.1:3540	
EC-1676-S.NO:074V0	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0x00049023	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6fb-custom	8910e1b0c0dd86bcbf8757c4dd36da13	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.032V	OK	http://127.0.0.1:3540	
Input Current	1.752A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 62%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.208.41	Netmask: 255.255.255.224, Broadcast: 10.244.208.63	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	28.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e9916d5e6ea6812b4	http://127.0.0.1:3540	
GPU Temperature	28 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027e9916d5e6ea6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: SB 1928 98th Ave
Date: 07-14-2026


Site ID : OAKF033

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				X
Ekin Traffic System	1.0.7.705.02	94e388a24c324ce8a890333366ecfa564234f72a8ab86db3f99718e6770fd04b		
Client Code	1.0.7.705.02	CAQAK		
Location	1.0.7.705.02	S9 1928 98TH AVE		
Site Id	1.0.7.705.02	OAKF033		
Container Code	1.0.7.705.02	OAKF033		
Product Serial Number	1.0.7.705.02	BS250803727		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU XB-CB	XB_1.5.3	S. No: 1421425037602	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916d5c6ca6812b4	http://127.0.0.1:3540	
EO-1676-S.NO:0854R	1.0	http://127.0.0.1:9590/ekinCamera	http://127.0.0.1:3540	
Speed Sensor	FSS-244	S. No: 0x000488C5	http://127.0.0.1:3540	
Speed Sensor	FSS-244	FW: 4.03.08.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	FSS-244	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epron	2.1.176.1df4e6f9-custom	8910e1b0c0dd84bcbf8757c4dd36da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.022V	OK	http://127.0.0.1:3540	
Input Current	1.464A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.2T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.240.201	Netmask: 255.255.255.224, Broadcast: 10.244.240.229	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	30 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916d5c6ca6812b4	http://127.0.0.1:3540	
GPU Temperature	29.5 °C	852dcff2d22b8a27ddac72a6686c74992fe3f262dd6a027c3916d5c6ca6812b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: EB 6161 Bancroft Ave
Date: 07-16-2026


Site ID : OAKF034

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





TECHNICIAN SERVICE AND INSPECTION LOG


System info page

System Info				✕
Skin Traffic System	1.0.7.705.02	ede024d7208b89bf3350b9f4f9b6f9a7dcbce509ead532e2288c3d4ece727a		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	EB 6161 BANCROFT AVE		
Site Id	1.0.7.705.02	OAKF034		
Container Code	1.0.7.705.02	OAKF034		
Product Serial Number	1.0.7.705.02	B0250803726		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
EPU XB-CB	XB_1.5.3	S. No: 1421425037719	http://127.0.0.1:3540	
Radar Server	1.0.7.705.02	852d4f2d22b8c27d4ec72a6686c749929c3f263d86e027e2916d5efead612b4	http://127.0.0.1:3540	
EO-1676-S.NO.07NCT	1.0	http://127.0.0.1:9590/skinCamera	http://127.0.0.1:3540	
Speed Sensor	F55-344	S. No: 6a00548054	http://127.0.0.1:3540	
Speed Sensor	F55-344	FW- 4.03.06.0 - [9]	http://127.0.0.1:3540	
Speed Sensor	F55-344	Checksum: 0X0000000010481A56	http://127.0.0.1:3540	
Epmn	2.1.176.1d4e6f9-custom	8910e1b0cd86b6b0c9757c4d436da12	http://127.0.0.1:3540	
Camera Manager	1.1.17	OK	http://127.0.0.1:3540	
Input Voltage	5.032V	OK	http://127.0.0.1:3540	
Input Current	1.776A	OK	http://127.0.0.1:3540	
External Storage Usage	1.8T 1.4T 79%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Internal Storage Usage	40G 24G 60%	OK(Folder Size/Partition Used/Partition Total Ratio)	http://127.0.0.1:3540	
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255	http://127.0.0.1:3540	
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255	http://127.0.0.1:3540	
Network Configuration	10.244.241.201	Netmask: 255.255.255.224, Broadcast: 10.244.241.223	http://127.0.0.1:3540	
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255	http://127.0.0.1:3540	
Network Configuration	127.0.0.1	Netmask: 255.0.0.0	http://127.0.0.1:3540	
Overview	192.168.12.16	Accessible	http://127.0.0.1:3540	
Ntp Service	1.0	OK	http://127.0.0.1:3540	
CPU Temperature	28.5 °C	852d4f2d22b8c27d4ec72a6686c749929c3f263d86e027e2916d5efead612b4	http://127.0.0.1:3540	
GPU Temperature	30 °C	852d4f2d22b8c27d4ec72a6686c749929c3f263d86e027e2916d5efead612b4	http://127.0.0.1:3540	
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo



VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

Approach Information

Location Address: WB 6130 Bancroft Ave
Date: 07-16-2026


Site ID : OAKF035

Physical Inspection Checklist

Check for vandalism & graffiti: Inspect YES
Housing, poles Locked & secured upon arrival: Clean camera YES
Enforcement signs Present YES
System functionality Verified YES

Additional Notes





VERRA MOBILITY

TECHNICIAN SERVICE AND INSPECTION LOG

System info page

System Info				
Disk Traffic System	1.0.7.705.02	e8dc222f186ca4b7626ef9b6a70ca1f62f1e579092216841e265c9c5d7da03e		
Client Code	1.0.7.705.02	CAOAK		
Location	1.0.7.705.02	WB 6130 BANCROFT AVE		
Site Id	1.0.7.705.02	OAKF085		
Container Code	1.0.7.705.02	OAKF085		
Product Serial Number	1.0.7.705.02	98290602543		
Product Code	1.0.7.705.02	E.02.3.0001 - A43		
GPU X8-CB	X8_1.5.3	S. No: 1423724321432		http://1127.0.0.1:3540
Radar Server	1.0.7.705.02	852dcff2d22b8e27ddac72a6686c74992fe3f262d86a027e3916d5efead812b4		http://1127.0.0.1:3540
EO-1676-SNO-S76WM	1.0	http://1127.0.0.1:9990/ehinCamera		http://1127.0.0.1:3540
Speed Sensor	F59-244	S. No: 0a00048ESC		http://1127.0.0.1:3540
Speed Sensor	F59-244	FW: 4.03.08.0 - [6]		http://1127.0.0.1:3540
Speed Sensor	F59-244	Checksum: 0X0000000010481A56		http://1127.0.0.1:3540
Egon	2.1.176.1d94edf9-custom	8910e1b0c0d486b6e9757e44636da13		http://1127.0.0.1:3540
Camera Manager	1.1.17	OK		http://1127.0.0.1:3540
Input Voltage	5.022V	OK		http://1127.0.0.1:3540
Input Current	1.792A	OK		http://1127.0.0.1:3540
External Storage Usage	1.8T 1.3T 78%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://1127.0.0.1:3540
Internal Storage Usage	40G 24G 63%	OK(Folder Size/Partition Used/Partition Total Ratio)		http://1127.0.0.1:3540
Network Configuration	172.17.0.1	Netmask: 255.255.0.0, Broadcast: 172.17.255.255		http://1127.0.0.1:3540
Network Configuration	192.168.10.10	Netmask: 255.255.255.0, Broadcast: 192.168.10.255		http://1127.0.0.1:3540
Network Configuration	10.244.242.201	Netmask: 255.255.255.234, Broadcast: 10.244.242.229		http://1127.0.0.1:3540
Network Configuration	192.168.12.10	Netmask: 255.255.255.0, Broadcast: 192.168.12.255		http://1127.0.0.1:3540
Network Configuration	127.0.0.1	Netmask: 255.0.0.0		http://1127.0.0.1:3540
Overview	192.168.12.16	Accessible		http://1127.0.0.1:3540
Http Service	1.0	OK		http://1127.0.0.1:3540
CPU Temperature	26 °C	852dcff2d22b8e27ddac72a6686c74992fe3f262d86a027e3916d5efead812b4		http://1127.0.0.1:3540
GPU Temperature	26.5 °C	852dcff2d22b8e27ddac72a6686c74992fe3f262d86a027e3916d5efead812b4		http://1127.0.0.1:3540
Violation Enabled	1.0.7.705.02	Yes		

By signing this document, you acknowledge that you performed the checks specified on this form and attest that the forgoing information is true and correct.

Signature of Physical Technician

Printed Name Victor Galindo